

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21005320/R1TF3E2

Date: 19/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993659
Claimant Vehicle No : SKH2564D Insured Vehicle No : SCV988Z
Date of Loss: 26/04/2021 Nature of Claim: TP Claim No: 9812715698SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKH2564D**
Make & Model: HONDA STREAM, 1.8 X (A) Engine No: R18A2101457
Reg. Date: 20/11/2012 (Man. Year: 2009) Chassis No: RN63101380
Colour: Blue Odometer: 196226 km
Engine Capacity: 1799 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Landsail 6 mm Rear Left Side: Landsail 6 mm
Front Right Side: Landsail 6 mm Rear Right Side: Landsail 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/04/2021
Date Inspected: 30/04/2021 Inspected At: Car Laboratories Pte Ltd (HQ)
1 BUKIT BATOK CRESCENT, #04-56 WCEGA
PLAZA
Singapore 658064
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$28,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	0.00 F	*- F	
2	1		*REAR BUMPER TOW COVER	Deformed	0.00 F	*- F	
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
4	1		*REVERSE SENSOR	Not Working	0.00 F	*- F	
5	1		*TAILGATE	Bent	0.00 F	*- F	
6	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F	
					Total Parts (\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >