

# AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aacls.com

Company Registration No.: 201325787M

GST Reg. No.: 201325787M



bigSAFE<sub>4</sub>

## Quotation

DATE: 12-May-21

TERMS: 30 Days

PAGE NO.: Page 1 of 1

TO:

China Taiping Insurance (S) Pte Ltd - Claims Dept  
3 Anson Rd,  
#16-00 Springleaf Tower  
Singapore 079909

| S/N | DESCRIPTION                                       | UOM | QTY | UNIT PRICE | AMOUNT (\$) |
|-----|---------------------------------------------------|-----|-----|------------|-------------|
|     | <b>Own Damage Repair : XE1401J DOA: 21/04/21</b>  |     |     |            |             |
| 1   | Front Panel <i>bt</i>                             |     | 1   | 5,177.32   | \$ 5,177.32 |
| 2   | Front Panel Hinge - LH <i>cm</i>                  |     | 1   | 93.2       | \$ 93.20    |
| 3   | Front Panel Lock Assy <i>x</i>                    |     | 1   | 162.99     | \$ 162.99   |
| 4   | Front Panel Lock Hook <i>x</i>                    |     | 1   | 30.33      | \$ 30.33    |
| 5   | Front Grille Upper <i>cm</i>                      |     | 1   | 521.79     | \$ 521.79   |
| 6   | Front Grille Lower <i>mis</i>                     |     | 1   | 727.97     | \$ 727.97   |
| 7   | Emblem "Mit" <i>cm</i>                            |     | 1   | 195.95     | \$ 195.95   |
| 8   | Emblem "FUSO" <i>cm</i>                           |     | 1   | 295.33     | \$ 295.33   |
| 9   | Wiper Arm <i>bt</i>                               |     | 1   | 155.25     | \$ 155.25   |
| 10  | Wiper Blade <i>cm</i>                             |     | 1   | 66.74      | \$ 66.74    |
| 11  | Wiper Link Assy <i>?</i>                          |     | 1   | 604.12     | \$ 604.12   |
| 12  | Front Windscreen Glass <i>cm</i>                  |     | 1   | 1,680.05   | \$ 1,680.05 |
| 13  | Front Windscreen Glass Rubber Seal <i>cm</i>      |     | 1   | 670.89     | \$ 670.89   |
| 14  | Front Corner Panel - LH <i>cm</i>                 |     | 1   | 468.21     | \$ 468.21   |
| 15  | Front Corner Panel Lower Bracket - LH <i>?</i>    |     | 1   | 107        | \$ 107.00   |
| 16  | Front Corner Panel Center Bracket - LH <i>?</i>   |     | 1   | 32.78      | \$ 32.78    |
| 17  | Front Corner Panel Lamp - LH <i>cm</i>            |     | 1   | 195.03     | \$ 195.03   |
| 18  | Front Corner Panel Bottom Rubber Seal LH <i>?</i> |     | 1   | 84.23      | \$ 84.23    |
| 19  | Front Bumper <i>bt</i>                            |     | 1   | 2,259.31   | \$ 2,259.31 |
| 20  | Front Bumper Cover <i>mis</i>                     |     | 1   | 611.78     | \$ 611.78   |
| 21  | Front Bumper Side - LH <i>cm</i>                  |     | 1   | 140.29     | \$ 140.29   |
| 22  | Front Bumper Lower Stay <i>?</i>                  |     | 1   | 169.07     | \$ 169.07   |
| 23  | Front Bumper Bracket - LH <i>?</i>                |     | 1   | 37.3       | \$ 37.30    |
| 24  | Front Bumper Step Garnish <i>cm</i>               |     | 1   | 217.26     | \$ 217.26   |
| 25  | Front Center Bumper <i>de</i>                     |     | 1   | 273.12     | \$ 273.12   |
| 26  | Front Center Side Bumper - LH <i>?</i>            |     | 1   | 193.04     | \$ 193.04   |
| 27  | Front Bumper Side Air Dust - LH <i>?</i>          |     | 1   | 96.7       | \$ 96.70    |
| 28  | Headlamp Assy - LH <i>cm</i>                      |     | 1   | 1,286.45   | \$ 1,286.45 |
| 29  | Headlamp Rim - LH <i>cm</i>                       |     | 1   | 181.18     | \$ 181.18   |
| 30  | Headlamp Aluminium Bracket - LH <i>cm</i>         |     | 1   | 947.63     | \$ 947.63   |
| 31  | Fog Lamp Assy - LH <i>cm</i>                      |     | 1   | 293.25     | \$ 293.25   |
| 32  | Fog Lamp Rim - LH <i>cm</i>                       |     | 1   | 186.05     | \$ 186.05   |
| 33  | Step Panel Top - LH <i>cm</i>                     |     | 1   | 324.55     | \$ 324.55   |
| 34  | Step Panel Lower - LH <i>cm</i>                   |     | 1   | 270.56     | \$ 270.56   |
| 35  | Step Panel Under Cover - LH <i>cm</i>             |     | 1   | 229.87     | \$ 229.87   |
| 36  | Step Alloy Step Mat - LH <i>?</i>                 |     | 2   | 652        | \$ 1,304.00 |
| 37  | Stand Panel - LH <i>?</i>                         |     | 1   | 744.59     | \$ 744.59   |
| 38  | Stand Panel Alloy Mat - LH <i>?</i>               |     | 1   | 324.55     | \$ 324.55   |
| 39  | Stand Panel Bracket - LH <i>?</i>                 |     | 1   | 254.7      | \$ 254.70   |
| 40  | Front Fender - LH <i>x</i>                        |     | 1   | 1,117.80   | \$ 1,117.80 |
| 41  | Front Fender Garnish - LH <i>x</i>                |     | 1   | 205.56     | \$ 205.56   |

# AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aakls.com

Company Registration No.: 201325787M

GST Reg. No.: 201325787M



bigSAFE<sub>4</sub>

## Quotation

DATE: 12-May-21

TERMS: 30 Days

PAGE NO.: Page 1 of 1

TO:

China Taiping Insurance (S) Pte Ltd - Claims Dept  
3 Anson Rd,  
#16-00 Springleaf Tower  
Singapore 079909

| S/N        | DESCRIPTION                                                                       | UOM | QTY | UNIT PRICE       | AMOUNT (\$)        |
|------------|-----------------------------------------------------------------------------------|-----|-----|------------------|--------------------|
|            | <b>Own Damage Repair : XE1401J DOA: 21/04/21</b>                                  |     |     |                  |                    |
| 42         | Front Fender Bracket - LH                                                         |     | 1   | 232.59           | \$ 232.59          |
| 43         | Side Mirror Stay - LH                                                             |     | 1   | 817.09           | \$ 817.09          |
| 44         | Side Mirror (Big) - LH                                                            |     | 1   | 177.68           | \$ 177.68          |
| 45         | Side Mirror (Square) - LH                                                         |     | 1   | 159.83           | \$ 159.83          |
| 46         | Side Mirror (Small) - LH                                                          |     | 1   | 107.24           | \$ 107.24          |
| 47         | Side Mirror Stay Top - LH                                                         |     | 1   | 316.31           | \$ 316.31          |
| 48         | Cabin Rear Corner Panel - LH                                                      |     | 1   | 2,154.21         | \$ 2,154.21        |
| 49         | Cabin Rear Corner Inner Panel - LH                                                |     | 1   | 748.51           | \$ 748.51          |
| 50         | Cabin Rear Corner Inner Panel Garnish - LH                                        |     | 1   | 287.37           | \$ 287.37          |
| 51         | Cabin Rear Corner Side Trim - LH                                                  |     | 1   | 1,312.39         | \$ 1,312.39        |
| 52         | Cabin Rear Panel Glass                                                            |     | 1   | 1,432.00         | \$ 1,432.00        |
| 53         | Cabin Rear Panel Glass Rubber Seal                                                |     | 1   | 230.72           | \$ 230.72          |
| 54         | Aircond Suction Pipe                                                              |     | 1   | 338.25           | \$ 338.25          |
| 55         | Aircond Discharge Hose                                                            |     | 1   | 334.76           | \$ 334.76          |
| 56         | Aircond Condensor Assy                                                            |     | 1   | 3,497.39         | \$ 3,497.39        |
| 57         | Aircond Condensor Fan Motor Assy                                                  |     | 1   | 528.17           | \$ 528.17          |
| 58         | Aircond Condensor Fan Cowling                                                     |     | 1   | 362.01           | \$ 362.01          |
| 59         | Aircond Condensor Hose Assy                                                       |     | 1   | 199.74           | \$ 199.74          |
| 60         | Labour to repair whole cabin, dismantle & renew all parts JOB to spray & painting |     | 1   | \$5,000.00       | \$ 5,000.00        |
| E. & O. E. |                                                                                   |     |     | <b>SUB-TOTAL</b> | <b>\$41,174.05</b> |
|            |                                                                                   |     |     | <b>7% GST</b>    | <b>\$2,882.18</b>  |
|            |                                                                                   |     |     | <b>TOTAL</b>     | <b>\$44,056.23</b> |

SGD:

Note:

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd."

Accepted and Confirmed by

AAK LOGISTICS SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

Company Chop & Signature

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature

Rafael  
Peijuan  
HP96010068  
14 days  
HS  
30/04/21 @ 1600  
EXCESS = 3000  
Repair  
Repair after repair