

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21005325/KPA3Q2  
**Date:** 08/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100463042
<b>Claimant Vehicle No :</b>	GBE9659R	<b>Insured Vehicle No :</b>	SLB8514D
Date of Loss:	13/05/2020	Nature of Claim:	TP
		Claim No:	2749991859SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBE9659R</b>	Engine No:	1KD2613688
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Chassis No:	JTFHT02P700196594
Reg. Date:	05/05/2016 (Man. Year: 2016)	Odometer:	169041 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,733.43	2,186.46	546.97	20.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,540.00	840.00	35.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,113.43</b>	<b>3,726.46</b>	<b>1,386.97</b>	<b>27.12</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,950.00</b>		

(S\$)	5,113.43	2,950.00	2,163.43	42.31
<b>+ GST 7.00/7.00% (S\$)</b>	357.94	206.50	151.44	42.31
<b>Nett Amount (S\$)</b>	<b>5,471.37</b>	<b>3,156.50</b>	<b>2,314.87</b>	<b>42.31</b>
<b>+ Loss of Use (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>(S\$)</b>		3,856.50		
<b>Liabie Amount (80.00%) (S\$)</b>		<b>3,085.20</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,087.20</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,050.00</b>		

INSPECTION

Date of Assignment: 30/04/2021

Date Inspected: 30/04/2021

Estimated Period of Repair: 6.0 days

 Inspected At: Alan's United Auto Pte Ltd (HQ)  
 Blk 7 Sin Ming Industrial Estate, #01-76  
 Singapore 575642
**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S SLIDING DOOR	Bent	1,445.78 FL	*1,445.78 FL
2	1		*N/S REAR FENDER	Bent	1,469.50 FL	*1,469.50 FL
3	1		*REAR BUMPER	Repair	373.10 FL	*- FL
4	1		*N/S ROCKER PANEL	Repair	356.20 FL	*- FL
					<b>Sub Total (\$\$)</b>	<b>2,915.28</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>728.82</b>
					<b>Total Parts (\$\$)</b>	<b>2,186.46</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO APPLY UNDERSEALING	New	80.00	60.00
2	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	100.00	80.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	1,000.00	600.00
4	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AVOBE PARTS	New	1,200.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>2,380.00</b>	<b>1,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >