

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/GRB21002855/R1TF3E2-1**Date:** 07/06/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SLQ6033J	<b>Insured Vehicle No :</b>	SLX781K
Date of Loss:	01/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000944

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLQ6033J</b>	Engine No:	LEB5948484
Make & Model:	HONDA VEZEL, 1.5 CVT ABS D/AIRBAG 2WD 5DR (A)	Chassis No:	RU31248467
Reg. Date:	17/07/2017 (Man. Year: 2017)	Odometer:	102844 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R15	Rear Tyre Size:	215/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	17,165.52	6,018.28	11,147.24	64.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	2,650.00	1,130.00	29.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,945.52</b>	<b>8,668.28</b>	<b>12,277.24</b>	<b>58.62</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,900.00</b>		
<b>(S\$)</b>	20,945.52	6,900.00	14,045.52	67.06
<b>+ GST 7.00/7.00% (S\$)</b>	1,466.19	483.00	983.19	67.06
<b>Nett Amount (S\$)</b>	<b>22,411.71</b>	<b>7,383.00</b>	<b>15,028.71</b>	<b>67.06</b>

INSPECTION

Date of Assignment:	30/04/2021	
Date Inspected:	05/03/2021	Inspected At: V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center Singapore 627605
Estimated Period of Repair:	8.0 days	

**Adjuster:** MOHD RASUL**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 07 Jun 2021)

**Parts:** 144 HONDA VEZEL 1.5 CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLQ6033J)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT HEADLAMP L/R	Repair	3,569.00 FL	*- FL
2	1		*FRONT GRILLE	Cracked	387.80 FL	*387.80 FL
3	1		*FRONT GRILLE LOGO EMBLEM	Necessary	28.90 FL	*28.90 FL
4	1		*FRONT GRILLE CHROME MOULDING	Serviceable	98.00 FL	*- FL
5	1		*FRONT GRILLE OUTER GARNISH	Cracked	421.00 FL	*421.00 FL
6	2		*FRONT GRILLE BRACKET L/R	Serviceable	70.00 FL	*- FL
7	1		*FRONT BUMPER	Cracked	801.70 FL	*801.70 FL
8	2		*FRONT BUMPER FOGLAMP BRACKET L/R	Serviceable	100.00 FL	*- FL
9	2		*FRONT BUMPER FOGLAMP GARNISH L/R	Serviceable	90.00 FL	*- FL
10	2		*FRONT BUMPER FOGLAMP L/R	Serviceable	655.40 FL	*- FL
11	1		*FRONT BUMPER LOWER CENTER GRILLE	Serviceable	77.70 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT TOP GARNISH L/R	O/S Cracked	48.40 FL	*24.20 FL
13	3		*FRONT BUMPER REINFORCEMENT TOP GARNISH CLIPS	Not Necessary	19.50 FL	*- FL
14	1		*FRONT BUMPER REINFORCEMENT	Repair	321.00 FL	*- FL
15	2		*FRONT BUMPER SIDE RETAINER L/R	Serviceable	39.20 FL	*- FL
16	1		*FRONT BUMPER TOW HOOK COVER	Repair	13.90 FL	*- FL
17	1		*FRONT BUMPER UNDER LOWER RUBBER MOULDING	Serviceable	84.90 FL	*- FL
18	1		*FRONT BUMPER LOWER LIP	Serviceable	381.00 FL	*- FL
19	1		*REAR TAILGATE	Bent	953.30 FL	*953.30 FL
20	2		*REAR TAILGATE HINGES L/R	Serviceable	100.00 FL	*- FL
21	2		*REAR TAILGATE DAMPER L/R	Serviceable	360.00 FL	*- FL
22	1		*REAR TAILGATE SPOILER	Serviceable	480.00 FL	*- FL
23	1		*REAR TAILGATE THIRD BRAKE LAMP	Serviceable	202.00 FL	*- FL
24	1		*REAR TAILGATE INNER TRIM GARNISH	Cracked	153.40 FL	*153.40 FL
25	2		*REAR TAILGATE INNER TRIM GARNISH L/R	Serviceable	100.00 FL	*- FL
26	1		*REAR TAILGATE INNER UPPER TRIM GARNISH	Serviceable	85.00 FL	*- FL
27	1		*REAR TAILGATE WINDSCREEN GLASS	Not Necessary	1,150.00 FL	*- FL
28	1		*REAR TAILGATE WINDSCREEN INNER SEAL	Necessary	100.00 FL	*100.00 FL
29	2		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	100.00 FL	*100.00 FL
30	1		*REAR TAILGATE OUTER GARNISH	Cracked	220.00 FL	*220.00 FL
31	1		*REAR TAILGATE OUTER GARNISH H LOGO EMBLEM	Necessary	25.00 FL	*25.00 FL
32	1		*REAR TAILGATE REVERSE CAMERA	Serviceable	819.60 FL	*- FL
33	1		*REAR TAILGATE WIPER ARM	Not Necessary	42.00 FL	*- FL
34	1		*REAR TAILGATE WIPER ARM BLADE	Not Necessary	18.00 FL	*- FL
35	1		*REAR TAILGATE WIPER ARM COVER	Not Necessary	22.00 FL	*- FL
36	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	205.00 FL	*- FL
37	2		*REAR TAILGATE REFLECTOR L/R	Serviceable	826.40 FL	*- FL
38	2		*REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	Not Necessary	77.00 FL	*- FL
39	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Bent	37.00 FL	*37.00 FL
40	1		*REAR TAILGATE WEATHER STRIP	Cut	96.80 FL	*96.80 FL
41	2		*REAR TAILLAMP L/R	Cracked	949.20 FL	*949.20 FL
42	8		*REAR TAILLAMP CLIPS L/R	Necessary	52.00 FL	*52.00 FL
43	2		*REAR TAILLAMP BACK RUBBER GASKET L/R	Necessary	139.00 FL	*139.00 FL
44	2		*REAR TAILLAMP INNER PANEL L/R	Serviceable	270.00 FL	*- FL
45	2		*REAR FENDER INNER TRIM BOARD L/R	Serviceable	590.00 FL	*- FL
46	2		*REAR FENDER WHEEL ARCH GARNISH L/R	Bent	390.00 FL	*390.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BUMPER	Cracked	762.70 FL	*762.70 FL
48	2		*REAR BUMPER SIDE L/R	Cracked	390.00 FL	*390.00 FL
49	2		*REAR BUMPER SIDE RETAINER L/R	Serviceable	29.00 FL	*- FL
50	2		*REAR BUMPER REFLECTOR L/R	Serviceable	282.20 FL	*- FL
51	1		*REAR END PANEL INNER TOP GARNISH	Cracked	98.00 FL	*98.00 FL
52	4		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	26.00 FL	*26.00 FL
53	1		*REAR END PANEL LOCK STRIKER	Bent	27.50 FL	*27.50 FL
54	1		*REAR END PANEL INNER TAILGATE ANTENNA SENSOR	Serviceable	80.00 FL	*- FL
55	1		*REAR END PANEL OUTER TAILGATE BUZZER	Serviceable	85.00 FL	*- FL
56	1		*REAR END PANEL	Bent	415.60 FL	*415.60 FL
57	1		*REAR SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	Serviceable	430.30 FL	*- FL
58	1		*REAR SPARE TYRE PANEL INNER TOP STORAGE BOX	Cracked	230.00 FL	*230.00 FL
59	1		*REAR SPARE TYRE PANEL LOWER UNDER COVER	Serviceable	190.00 FL	*- FL
60	1		*REAR EXHAUST SILENCER BOX	Repair	528.00 FL	*- FL
61	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
62	2		*SET FRONT FENDER ARCH GARNISH CLIPS L/R	Necessary	60.00 FS	*40.00 FS
63	1		*FRONT GRILLE NUMBER PLATE	Serviceable	25.00 FS	*- FS
64	1		*FRONT GRILLE NUMBER PLATE HOLDER	Serviceable	50.00 FS	*- FS
65	1		*SET REAR TAILGATE SPOILER CLIPS	Necessary	30.00 FS	*30.00 FS
66	1		*SET REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
67	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
68	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
69	1		*REAR TAILGATE NUMBER PLATE }	Bent	25.00 FS	*35.00 FS
70	1		*REAR TAILGATE NUMBER PLATE HOLDER }	Cracked	50.00 FS	*- FS
71	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
72	1		*REAR TAILGATE REVERSE CAMERA	Serviceable	750.00 FS	*- FS
73	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Not Necessary	60.00 FS	*- FS
74	2		*SET REAR FENDER WHEEL ARCH GARNISH CLIPS L/R	Necessary	60.00 FS	*40.00 FS
75	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
76	1		*SET REAR BUMPER REVERSE SENSOR	Cracked	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>21,034.40</b>	<b>7,384.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	3,868.88	1,365.82
<b>Total Parts (\$)</b>	<b>17,165.52</b>	<b>6,018.28</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PROVIDE TOWING CHARGE	New	50.00	50.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	140.00	60.00
3	TO REMOVE, REINSTALL TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET	New	100.00	60.00
4	TO REMOVE, REINSTALL TAILGATE WINDSCREEN	New	140.00	120.00
5	TO RESET SYSTEM AFTER REPAIR WORKS	New	350.00	100.00
6	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,300.00	1,000.00
7	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,600.00	1,200.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	60.00
			<b>Gross Labour Cost (S\$)</b>	<b>3,780.00</b>
				<b>2,650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >