

**ASSESSMENT REPORT FOR VEHICLE NO. SLQ 6033 J**

**PARTS (LIST ITEMS)**

Qty	Description	Condition	Workshop's Estimate	Our Assessment
2	FRONT HEADLAMP L/R	Repair	3,569.00	-
1	FRONT GRILLE	Cracked	387.80	387.80
1	FRONT GRILLE 'LOGO' EMBLEM	Necessary	28.90	28.90
1	FRONT GRILLE CHROME MOULDING <b>xsvc</b>	Cracked	98.00	98.00 <b>X</b>
1	FRONT GRILLE OUTER GARNISH	Cracked	421.00	421.00
2	FRONT GRILLE BRACKET L/R <b>xsvc</b>	Bent	70.00	70.00 <b>X</b>
1	FRONT BUMPER	Cracked	801.70	801.70
2	FRONT BUMPER FOGLAMP BRACKET L/R <b>xsvc</b>	Bent	100.00	100.00 <b>X</b>
2	FRONT BUMPER FOGLAMP GARNISH L/R <b>xsvc</b>	Bent	90.00	90.00 <b>X</b>
1	FRONT BUMPER FOGLAMP L/R <b>xsvc</b>	Cracked	655.40	655.40 <b>X</b>
1	FRONT BUMPER LOWER CENTER GRILLE <b>xsvc</b>	Cracked	77.70	77.70 <b>X</b>
2	FRONT BUMPER REINFORCEMENT TOP GARNISH L/R <b>RH-cra(1pc)</b>	Cracked	48.40	<b>24.20</b> 48.40
3	FRONT BUMPER REINFORCEMENT TOP GARNISH CLIPS <b>xnn</b>	Necessary	19.50	19.50 <b>X</b>
1	FRONT BUMPER REINFORCEMENT <b>xsvc</b>	Repair	321.00	- <b>xR</b>
2	FRONT BUMPER SIDE RETAINER L/R <b>xsvc</b>	Bent	39.20	39.20 <b>X</b>
1	FRONT BUMPER TOW HOOK COVER <b>repair</b>	Necessary	13.90	13.90 <b>xR</b>
1	FRONT BUMPER UNDER LOWER RUBBER MOULDING <b>xsvc</b>	Cracked	84.90	84.90 <b>X</b>
1	FRONT BUMPER LOWER LIP <b>xsvc</b>	Cracked	381.00	381.00 <b>X</b>
1	REAR TAILGATE	Bent	953.30	953.30
2	REAR TAILGATE HINGES L/R <b>xsvc</b>	Bent	100.00	100.00 <b>X</b>
2	REAR TAILGATE DAMPER L/R <b>xsvc</b>	Bent	360.00	360.00 <b>X</b>
1	REAR TAILGATE SPOILER <b>xsvc</b>	Repair	480.00	- <b>X</b>
1	REAR TAILGATE THIRD BRAKE LAMP <b>xsvc</b>	Reuse	202.00	- <b>X</b>
1	REAR TAILGATE INNER TRIM GARNISH	Cracked	153.40	153.40
2	REAR TAILGATE INNER TRIM GARNISH L/R <b>xsvc</b>	Repair	100.00	- <b>X</b>
1	REAR TAILGATE INNER UPPER TRIM GARNISH <b>xsvc</b>	Repair	85.00	- <b>X</b>
1	REAR TAILGATE WINDSCREEN GLASS <b>xnn</b>	Reuse	1,150.00	- <b>X</b>
1	REAR TAILGATE WINDSCREEN INNER SEAL	Necessary	100.00	100.00
2	REAR TAILGATE WINDSCREEN MOULDING	Necessary	100.00	100.00
1	REAR TAILGATE OUTER GARNISH	Cracked	220.00	220.00
1	REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM	Necessary	25.00	25.00
1	REAR TAILGATE REVERSE CAMERA <b>xsvc</b>	Faulty	819.60	819.60 <b>X</b>
			<b>3215.30</b>	
			<b>20%</b>	
			<b>2572.24</b>	

**ASSESSMENT REPORT FOR VEHICLE NO. SLQ 6033 J**

1	REAR TAILGATE WIPER ARM <b>xnn</b>	Bent	42.00	42.00 X
1	REAR TAILGATE WIPER ARM BLADE <b>xnn</b>	Bent	18.00	18.00 X
1	REAR TAILGATE WIPER ARM COVER <b>xnn</b>	Cracked	22.00	22.00 X
1	REAR TAILGATE WIPER MOTOR <b>xnn</b>	Faulty	205.00	205.00 X
2	REAR TAILGATE REFLECTOR L/R <b>xsvc</b>	Cracked	826.40	826.40 X
2	REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R <b>xnn</b>	Necessary	77.00	77.00 X
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R	Bent	37.00	37.00
1	REAR TAILGATE WEATHER STRIP	Cut	96.80	96.80
2	REAR TAILLAMP L/R	Cracked	949.20	949.20
8	REAR TAILLAMP CLIPS L/R	Necessary	52.00	52.00
2	REAR TAILLAMP BACK RUBBER GASKET L/R	Necessary	139.00	139.00
2	REAR TAILLAMP INNER PANEL L/R <b>xsvc</b>	Repair	270.00	- X
2	REAR FENDER INNER TRIM BOARD L/R <b>xsvc</b>	Repair	590.00	- X
2	REAR FENDER WHEEL ARCH GARNISH L/R	Bent	390.00	390.00
1	REAR BUMPER	Cracked	762.70	762.70
2	REAR BUMPER SIDE L/R	Cracked	390.00	390.00
2	REAR BUMPER SIDE RETAINER L/R <b>xsvc</b>	Bent	29.00	29.00 X
2	REAR BUMPER REFLECTOR L/R <b>xsvc</b>	Necessary	282.20	282.20 X
1	REAR END PANEL INNER TOP GARNISH	Cracked	98.00	98.00
4	REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	26.00	26.00
1	REAR END PANEL LOCK STRIKER	Bent	27.50	27.50
1	REAR END PANEL INNER TAILGATE ANTENNA SENSOR <b>xsvc</b>	Faulty	80.00	80.00 X
1	REAR END PANEL OUTER TAILGATE BUZZER <b>xsvc</b>	Faulty	85.00	85.00 X
1	REAR END PANEL	Bent	415.60	415.60
1	REAR SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD <b>xsvc</b>	Repair	430.30	- X
1	REAR SPARE TYRE PANEL INNER TOP STORAGE BOX	Cracked	230.00	230.00
1	REAR SPARE TYRE PANEL LOWER UNDER COVER <b>xsvc</b>	Cracked	190.00	190.00 X
1	REAR EXHAUST SILENCER BOX <b>repair</b>	Repair	528.00	- X

	<u>19,344.40</u>	<u>11,619.10</u>
Less 20% discount	3,868.88	2,323.82
Parts Total:	<u>15,475.52</u>	<u>9,295.28</u>

**3613.80**

**20%**

**2891.04**

**ASSESSMENT REPORT FOR VEHICLE NO. SLQ 6033 J**

**SPECIAL NETT ITEMS**

1	FRONT BUMPER CLIPS - SET	Necessary	30.00		30.00
2	FRONT FENDER ARCH GARNISH CLIPS L/R - SET <b>xnn</b>	Necessary	60.00	<b>40</b>	60.00
1	FRONT GRILLE NUMBER PLATE <b>xsvc</b>	Bent	25.00		25.00 <b>X</b>
1	FRONT GRILLE NUMBER PLATE HOLDER <b>xsvc</b>	Cracked	50.00		50.00 <b>X</b>
1	REAR TAILGATE SPOILER CLIPS - SET	Necessary	30.00		30.00
1	REAR TAILGATE WINDSCREEN INNER GARNISH CLIPS - SET	Necessary	30.00		30.00
1	REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00	<b>60</b>	80.00
1	REAR TAILGATE INNER TRIM BOARD CLIPS - SET	Necessary	30.00		30.00
1	REAR TAILGATE NUMBER PLATE	Bent	25.00	<b>35</b>	25.00
1	REAR TAILGATE NUMBER PLATE HOLDER	Cracked	50.00		50.00
1	REAR TAILGATE OUTER GARNISH CLIPS - SET	Necessary	30.00		30.00
1	REAR TAILGATE REVERSE CAMERA <b>xsvc</b>	Faulty	750.00		750.00 <b>X</b>
1	REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <b>xnn</b>	Necessary	60.00		60.00 <b>X</b>
2	REAR FENDER WHEEL ARCH GARNISH CLIPS L/R - SET	Necessary	60.00	<b>40</b>	60.00
1	REAR BUMPER CLIPS - SET	Necessary	30.00		30.00
1	REAR BUMPER REVERSE SENSOR - SET	Cracked	350.00	<b>200</b>	350.00
Special Nett Total :			1,690.00		1,690.00

**555**

**LABOUR**

S/N	Description		Workshop's Estimate		Our Assessment
1	To provide towing charge.		50.00		50.00
2	To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.		140.00	<b>60</b>	120.00
3	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.		100.00	<b>60</b>	80.00
4	To remove, reinstall tailgate windscreen.		140.00		120.00
5	To reset system after repair works.		350.00	<b>100</b>	300.00
6	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.		1,300.00	<b>1000</b>	1,200.00
7	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.		1,600.00	<b>1200</b>	1,500.00
8	To apply anti-rust chemical on repaired and replaced panel.		<b>2650</b>	<b>100.00</b>	<b>60</b> 80.00
Labour Total :			3,780.00		3,450.00
<b>TOTAL (PARTS &amp; LABOUR) \$</b>			20,945.52		14,435.28

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

**\$11,500.00 (SINGAPORE DOLLARS ELEVEN THOUSAND FIVE HUNDRED ONLY)**

**2572.40**  
**2891.04**  
**555.00**  
**2650.00**  


---

**8668.44**  
**20%**  
**6934.75**



Amas Ong  
Automobile Assessor

**L/S - \$ 6,900 / 8 days**