



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21005328/AUvf3n2	
			Date: 08/10/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMQ 4787T	Veh. Inspected	SJR 1628U
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2101369/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	30/04/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI AVANTE	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	KMH DU41BR9U771264	Colour	SILVER
	Odometer	267994 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	KAPSEN	6 mm
	L/H Front Tyre	195/65 R15	KAPSEN	6 mm
	R/H Rear Tyre	195/65 R15	KAPSEN	6 mm
	L/H Rear Tyre	195/65 R15	KAPSEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	29/04/2021	Inspection Date	30/04/2021
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	