

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21005332/KQF3E2

Date: 03/09/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00002172100		
Claimant Vehicle No :	SLC2025H	Insured Vehicle No :	SGN8082D		
Date of Loss:	28/04/2021	Nature of Claim:	TP	Claim No:	SNM21D202488/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC2025H	Engine No:	L15B4030848
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11110846
Reg. Date:	04/05/2016 (Man. Year: 2015)	Odometer:	46251 km
Colour:	Metallic Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,031.68	1,575.52	456.16	22.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,450.00	400.00	21.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,881.68</b>	<b>3,025.52</b>	<b>856.16</b>	<b>22.06</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,400.00</b>		
<b>Nett Amount (\$\$)</b>	<b>3,881.68</b>	<b>2,400.00</b>	<b>1,481.68</b>	<b>38.17</b>

### INSPECTION

Date of Assignment:	04/05/2021	
Date Inspected:	03/05/2021 Inspected At:	Cheong Cheong Motor Service (HQ) BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-293 SINGAPORE 569535 Singapore 569535
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Sep 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC2025H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT DOOR	Warped / Bent	917.20 FL	*917.20 FL
2	1		*FRONT RIGHT DOOR INNER LOCK	Repair	285.10 FL	*- FL
3	1		*REAR RIGHT DOOR	Warped / Bent	880.10 FL	*880.10 FL
4	1		*REAR RIGHT DOOR INNER LOCK	Repair	285.10 FL	*- FL
5	1		*REAR WHEEL ARCH	Cut	172.10 FL	*172.10 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	2,539.60 1,969.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	507.92 393.88
					Total Parts (S\$)	2,031.68 1,575.52

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	KNOCKING PUSH OUT RIGHT SIDE ACCIDENT PARTS STRIP / REFIT ABOVE ACCESSORIES	New	950.00	650.00
2	SPRAY PAINT & SPRAY ANTI-TUFF-KOTE ON RIGHT SIDE ACCIDENT AFFECTED AREAS	New	900.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,850.00</b>	<b>1,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >