

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21005339/KBS3Q2
Date: 18/10/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	FBL7703Y	Insured Vehicle No :	SLT9310Z
Date of Loss:	28/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001922

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL7703Y		
Make & Model:	YAMAHA XABRE, 150cc TFX150	Engine No:	G3G8E0030360
Reg. Date:	02/03/2017 (Man. Year: 2017)	Chassis No:	MH3RG3710HK024334
Colour:	Black	Odometer:	24518 km
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	150/60 R17
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,297.70	2,180.90	12,116.80	84.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	380.00	1,080.00	73.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,757.70	2,560.90	13,196.80	83.75
Approved Total (Overridden) (S\$)		2,050.00		

(S\$)	15,757.70	2,050.00	13,707.70	86.99
+ GST 7.00/7.00% (S\$)	1,103.04	143.50	959.54	86.99
Nett Amount (S\$)	16,860.74	2,193.50	14,667.24	86.99
+ Loss of Use (9.0 x S\$40.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		2,620.95		

INSPECTION

Date of Assignment: 30/04/2021

Date Inspected: 03/05/2021

Estimated Period of Repair: 4.0 days

Inspected At: Leong Auto Pte Ltd (HQ)
160 Sin Ming Drive, #02-13, Sin Ming Autocity
Singapore 575722**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Oct 2021)	
Parts:	N/A	YAMAHA XABRE 150cc TFX150 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL7703Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIDER FOOT REST R/H	Serviceable	68.00 FL	*- FL
2	1		*RIDER FOOT REST L/H	Dented	68.00 FL	*68.00 FL
3	1		*RIDER FOOT REST GRIP R/H	Serviceable	48.00 FL	*- FL
4	1		*RIDER FOOT REST GRIP L/H	Serviceable	48.00 FL	*- FL
5	1		*HANDLE BAR	Distorted	125.00 FL	*125.00 FL
6	1		*SET HANDLE BAR BALANCER	Dented	60.00 FL	*60.00 FL
7	1		*FRONT R/H BRAKE LEVER	Serviceable	48.00 FL	*- FL
8	1		*FRONT L/H BRAKE LEVER	Broken	48.00 FL	*48.00 FL
9	1		*FRONT R/H SIGNAL LAMP	Serviceable	95.00 FL	*- FL
10	1		*FRONT L/H SIGNAL LAMP	Serviceable	95.00 FL	*- FL
11	1		*FRONT HEAD LAMP	Serviceable	1,600.00 FL	*- FL
12	1		*FRONT FORK TUBE	Not Necessary	450.00 FL	*- FL
13	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
14	1		*FRONT CARBON FIBRE MUDGUARD }	Cracked	780.00 FS	*600.00 FS
15	1		*FRONT CARBON FIBRE L/H FAIRING }	Dented / Cut	680.00 FS	*- FS
16	1		*SET HANDLE BAR SIDE PROTECTOR }	Dented	380.00 FS	*- FS
17	1		*CARBON FIBRE EXHAUST PIPE PROTECTOR (SIDE)	Serviceable	850.00 FS	*- FS
18	1		*FRONT CARBON FIBRE R/H FAIRING	Serviceable	680.00 FS	*- FS
19	1		*SET SIDE STORAGE BOX	Dented / Cut	1,000.00 FS	*350.00 FS
20	1		*HELMET	Not Applicable	1,200.00 FS	*- FS
21	1		*REAR NUMBER PLATE	Serviceable	30.00 FS	*- FS
22	1		*FRONT FORK OIL	Not Necessary	60.00 FS	*- FS
23	1		*STEERING CONE & BEARING	Not Necessary	150.00 FS	*- FS
24	1		*BODY STICKER	Necessary	200.00 FS	*120.00 FS
25	2		*SIDE MIRROR	N/S Dented / O/S Missing	550.00 FS	*280.00 FS
26	1		*FRONT FORK	N/S Distorted	1,200.00 F	*600.00 FN
27	2		*FRONT FORK STAMP	Serviceable	760.00 F	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*FRONT FORK HOUSING COVER	Serviceable	1,200.00 F	*- FN
29	2		*REAR SEAT SIDE CARBON FIBRE COVER	Serviceable	2,000.00 F	*- FN
30	1		*FRONT NO PLATE	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	14,573.00	2,271.00
- List Item Discount on L Items 10.00/10.00% (S\$)	275.30	30.10
- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	60.00
Total Parts (S\$)	14,297.70	2,180.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT BODY ALIGHMENT	New	300.00	120.00
2	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR FENDERS AND REPLACE REAR DAMAGED PARTS	New	500.00	200.00
3	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	600.00	0.00
4	TO ADJUST FORK	New	60.00	60.00
Gross Labour Cost (\$\$)			1,460.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >