1/19/23, 12:32 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21005341/UPA3Q2

Date: 19/01/2023

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993808

Claimant Vehicle CRESSORY

CRESSORY

No: GBC7920J Insured Vehicle No: GBK6696X

Date of Loss: 21/04/2021 Nature of Claim: TP Claim No: 7834832416SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC7920J

Make & Model: TOYOTA HIACE, 3.0 D (M) Engine No: 1KD2313520

Reg. Date: 22/11/2013 (Man. Year: 2013) Chassis No: JTFHT02P700120602

Colour: Orange Odometer: 264074 km

Engine Capacity: 2982 cc Market Value/New Car

Market Value/New Car
Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Austone 7 mm Rear Left Side: Austone 7 mm
Front Right Side: Austone 7 mm Rear Right Side: Austone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,723.20	1,591.32	2,131.88	57.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	730.00	650.00	47.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,103.20	2,321.32	2,781.88	54.51
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	5,103.20	1,800.00	3,303.20	64.73
+ Loss of Use (4.0 x S	S\$80.00/day) (S\$)	320.00		
+ Doo	/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	2,127.45		

INSPECTION

Date of Assignment: 30/04/2021

Liu's Brother Auto Engineering Workshop (kaki

Bukit) (HQ)

Date Inspected: 30/04/2021 Inspected At: Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt

Singapore 417883, Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH SLIDING DOOR	Dented / Bent	1,455.10 F	*1,455.10 FL
2	1		*REAR RH FENDER	Repair	1,468.10 F	*-FL
3 F=Fra	1 inchise	part. S=Spc	*REAR RH CORPORATE ADVERTISEMENT & ARTWORK Nett. L=ListItemDisc.	Necessary	800.00 FS	*500.00 FS
				Sub Total (S\$)	3,723.20	1,955.10
			- List Item Discount on L Items 0	0.00/25.00% (S\$)	0.00	363.78
				Total Parts (S\$)	3,723.20	1,591.32
			Report was unsubmitted during this print-or	ut.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	30.00	0.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	600.00	250.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	700.00	450.00
4	TO APPLY RUST PROOFING RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	50.00	30.00
	Gross Labour Cost (S\$)		1,380.00	730.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >