

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005348/TGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900248033
Claimant Vehicle No :	SHA7772J	Insured Vehicle No :	SKP7280Y
Date of Loss:	29/04/2021	Nature of Claim:	TP
		Claim No:	9724605046SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7772J		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEKU405611
Reg. Date:	27/08/2020 (Man. Year: 2019)	Chassis No:	KMHC851CVLU189068
Colour:	Blue	Odometer:	101374 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	846.12	411.00	435.12	51.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	630.00	150.00	19.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,626.12	1,041.00	585.12	35.98
+ GST 7.00/7.00% (S\$)	113.83	72.87	40.96	35.98
Nett Amount (S\$)	1,739.95	1,113.87	626.08	35.98
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,641.44		

INSPECTION

Date of Assignment:	30/04/2021	
Date Inspected:	03/05/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Pandan) 45 Pandan Road Singapore 609286
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Repair	459.40 FL	*- FL
2	1		*MOULDING ASSY-RR BUMPER	Deformed	451.25 FL	*451.25 FL
3	10		*BUMPER COVER CLIP REAR	Not Necessary	22.00 FL	*- FL
4	1		*PROTECTOR MAT	Not Necessary	50.00 FS	*- FS
5	1		*NUMBER PLATE W/CASING	Cracked	50.00 FS	*50.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	1,032.65 501.25
					- List Item Discount on L Items 20.00/20.00% (\$)	186.53 90.25
					Total Parts (\$)	846.12 411.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (S\$)			780.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >