

REF:

From: _____ Date: _____

Veh No: SMN6200C Yr Regn: 2019, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle C.C. 1496

Colour White A/C: Insured / Std / NI / NA

Sp. Reading 16548 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK82001857 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 185/60R15

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. 06 mm	R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 30/04/21

Survey held at Xin Hua

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?☐: Prelim. Report

1)

☐ : Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

2)

Add Fee: : Site Insp (\$
$$S + RS \rightarrow SI$$

Photos

} Others

Report Format :

 Interview (\$)

☐ : Tech. Invs (3)

: Weekend (8)

Lump Sum / L.B.F.: \$

TOTAL