8/27/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/GRB21005350/EBS3Q2

Date:

SLQ8155C

27/08/2021

REFERENCE

Date of Loss:

Handling Insurer: India International Insurance Pte Ltd Policy No:

D21MFL0000447

Claimant Vehicle No:

GBH1408K 26/04/2021

Insured Vehicle No: Nature of Claim:

TP

Claim No: MFL2021D0001808

D4CBH294128

31807 km

KNCSJX76LH7185654

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH1408K**

Make & Model: HONDA ACCORD, 1.6 (M)

06/02/2018 (Man. Year: 2017) Reg. Date:

Colour: White 2497 cc

Engine Capacity: Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: Rear Left Side:

195 R15 Kumho 4 mm

Front Left Side: Front Right Side: Kumho 4 mm Kumho 4 mm

Rear Right Side:

Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,039.46	937.51	101.95	9.81
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,820.00	1,230.00	590.00	32.42
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,859.46	2,167.51	691.95	24.20
	Approved Total (Overridden) (S\$)		1,750.00		

Nett Amount (S\$) 2,859.46 1,750.00 1,109.46 38.80 0.00

Global Sum Settlement (S\$)

INSPECTION

Date of Assignment: 30/04/2021

Kuan Quek Motor (HQ) Date Inspected: Inspected At: Blk 3 Pioneer Road North, #01-16 10/05/2021

Singapore 628457

Estimated Period of Repair: 5.0 days

CHEN TSUE YEE Adjuster: Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jun 2021)

HONDA ACCORD 1.6 (M) (Catalogue:Merimen Singapore 1.0) Parts: 143

(Price-denominated Standard List) Labour: Repairer's

(Unsubmitted, no print-code for GBH1408K) **Print Code:**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR TAIL LAMP ASSY RH	Broken	176.86 F	*176.86 FL
2	1	*REAR NUMBER PLATE LAMP	Cut	26.00 F	*26.00 FL
3	1	*REAR TAIL GATE FRAME	Dented	537.00 F	*537.00 FL
4	1	*REAR TAIL GATE KIA MOTOR STICKER	Necessary	29.60 F	*29.60 FL
5	1	*SET REAR NUMBER PLATE AND RIM	Broken	50.00 F	*50.00 FL
6	1	*SET REAR SENSOR	Cut	220.00 FS	*200.00 FS
F=Fr	anchise part. S=SpcNett.	L=ListItemDisc.			
			Sub Total (S\$)	1,039.46	1,019.46
			- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	81.95
			Total Parts (S\$)	1,039.46	937.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REPLACE REAR SENSOR AND CHECK WIRING	New	120.00	30.00
2	TO RENEW REAR BUMPER GUARD	New	450.00	400.00
3	TO PANEL BEATING ,WELDING AND REPAIRING THE DAMAGED PARTS TO REMOVE AND CHARGE THE ABOVE PARTS	New	600.00	400.00
4	TO SPRAY PAINTING ON AFFECTED AREAS	New	650.00	400.00
	Gross La	oour Cost (S\$)	1,820.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >