

Shiau Chan (LKKAUTO)

From: TG Lim (LKK Auto)
Sent: Tuesday, 8 June 2021 11:00 am
To: Bryan Ang (LKKAUTO); Shiau Chan (LKKAUTO)
Subject: RE: CTI-TP SKT 3117S SURVEYED BY MR LIM

Hi Bryan,

Thank you very much for keeping me in the loop.

Can you please take another look at the survey photos DSCN 9037, 9038, 9039, 9040 and 9049 on the front head lamps.

If you still feel that the photos are not clear enough then it is alright with me.

At least I feel the right headlamp had clearer broken integral bracket.

But it's your call.

Best Regards
TG LIM

From: Bryan Ang (LKKAUTO)
Sent: Monday, 7 June, 2021 3:35 PM
To: Shiau Chan (LKKAUTO)
Cc: TG Lim (LKK Auto)
Subject: RE: CTI-TP SKT 3117S SURVEYED BY MR LIM

Hi

Rear right fender (no photo showing damages), rear fender inner trim x 2 (impact unlikely to cause the tear). To remove and re-offer.

No clear photos of damages to 2 front headlamps.

Best Regards,
Bryan Ang
LKK Auto Consultants Pte Ltd
phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Monday, 31 May 2021 8:58 AM
To: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>
Subject: CTI-TP SKT 3117S SURVEYED BY MR LIM

Dear Bryan,

For your audit.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

