



Your Ref : SNM21D201529/C01/THAMYL

Date: 18<sup>th</sup> May 2021

Our Ref : CS/CTI21005377/Gtf3e2

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE YM 9932L  
ACCIDENT ON 08/03/2021**

Instruction was received to inspect the vehicle Reg. No. YM 9932L. The inspection was conducted on 03/05/2021 at the premises of M/s Goldbell Engineering Pte Ltd, 10 Tuas Ave 18, Singapore 638894.

The following vehicle information was recorded:

Registration Number	: YM 9932L
Make/Model	: Nissan MKB37BLHRA
Year of Registration	: 2009
Body Colour	: White
Chassis Number	: MKB37BL00133
Engine Capacity	: 7684 cc

The vehicle sustained damages at the front portion and n/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 23,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 7,709.00)
Nett Liability	<u>S\$ 15,291.00</u> =====

Vehicle Inspected By:



XING GUO QIANG  
M.MATAI, AMSAE-A  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.