

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21005383/ATCN2**Date:** 07/09/2021**REFERENCE**

Insured/Claimant:	THAM JIA YONG, KEVIN	Policy No:	2070055890	
Date of Loss:	26/04/2021	Nature of Claim:	OD	Claim No: 1231436162SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT1833Y	Engine No:	CZD891778
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF36L1079544
Reg. Date:	30/03/2020 (Man. Year: 2020)	Odometer:	8543 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R17	Rear Tyre Size:	215/65R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,311.00	3,038.24	2,272.76	42.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,272.00	3,252.00	4,020.00	55.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,583.00	6,290.24	6,292.76	50.01
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	11,783.00	5,490.24	6,292.76	53.41
+ GST 7.00/7.00% (S\$)	824.81	384.32	440.49	53.41
Nett Amount (S\$)	12,607.81	5,874.56	6,733.25	53.41

INSPECTION

Date of Assignment:	03/05/2021		
Date Inspected:	28/04/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-LH	Dented	2,909.00 FS	*2,327.20 FS
2	1		*REAR DOOR OUTER DOOR SEAL-LH	Necessary	135.00 FS	*108.00 FS
3	1		*REAR DOOR CATCH	Not Necessary	120.00 FS	*- FS
4	1		*REAR DOOR INNER SEAL	Not Necessary	191.00 FS	*- FS
5	1		*REAR DOOR SILL PANEL SEAL-LH	Not Necessary	135.00 FS	*- FS
6	1		*REAR DOOR HANDLE-LH	Cut	198.00 FS	*158.00 FS
7	1		*REAR DOOR HOUSING CAP-LH	Cut	27.00 FS	*21.60 FS
8	1		*REAR DOOR WINDOW REGULATOR-LH	Not Necessary	282.00 FS	*- FS
9	1		*REAR DOOR WINDOW REGULATOR MOTOR-LH	Not Necessary	271.00 FS	*- FS
10	1		*REAR DOOR ARCH COVER-LH	Cut	257.00 FS	*205.20 FS
11	1		*REAR WHEEL ARCH COVER-LH	Cut	268.00 FS	*214.40 FS
12	1		*FRONT DOOR ARCH COVER-LH	Not Necessary	268.00 FS	*- FS
13	1		*SUNDRIES	Necessary	250.00 FS	*3.84 FS
					Total Parts (S\$)	5,311.00 3,038.24

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REINSTALL LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	400.00	280.00
3	TO DISMANTLE AND RENEW LHS RERA DOOR.TO REPAIR LHS FRONT DOOR,LHS REAR FENDER AND DOOR ENTRANCE.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	750.00
4	TO RESPRAY LHS REAR DOOR,LHS FRONT DOOR,LHS REAR FENDER,DOOR HANDLE AND DOOR ENTRANCE	New	3,600.00	1,750.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			7,272.00	3,252.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >