

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21005384/UPA3Q2
Date: 12/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MCV0006901
Claimant Vehicle No :	SLQ3535Y	Insured Vehicle No :	GBB7087U
Date of Loss:	01/05/2021	Nature of Claim:	TP
		Claim No:	MCV2021D0001971

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ3535Y	Engine No:	2ZR8024377
Make & Model:	TOYOTA C-HR, 1.8 S (A)	Chassis No:	ZYX102009174
Reg. Date:	05/07/2017 (Man. Year: 2017)	Odometer:	75724 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40Z R20	Rear Tyre Size:	245/40Z R20
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,329.20	4,853.72	11,475.48	70.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,430.00	2,000.00	58.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,759.20	6,283.72	13,475.48	68.20
Approved Total (Overridden) (S\$)		5,000.00		

Nett Amount (S\$)	19,759.20	5,000.00	14,759.20	74.70
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,407.45		
Global Sum Settlement (S\$)		5,400.00		

INSPECTION

Date of Assignment: 03/05/2021

Date Inspected: 03/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2021)
Parts:	M1-SUV	TOYOTA C-HR 1.8 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ3535Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Repair	1,819.20 F	*- FL
2	1		*FRONT DOOR OUTER PROTECTOR O/S	Torn	822.30 F	*380.20 FL
3	1		*SET FRONT DOOR FRAME BLACK STICKER O/S	Not Necessary	85.00 F	*- FL
4	1		*FRONT DOOR INNER RUBBER O/S	Not Necessary	211.20 F	*- FL
5	1		*REAR DOOR O/S	Dented	1,699.20 F	*1,280.10 FL
6	1		*REAR DOOR OUTER PROTECTOR O/S	Distorted	745.30 F	*299.50 FL
7	1		*SET REAR DOOR OUTER FRAME BLACK STICKER O/S	Necessary	85.00 F	*85.00 FL
8	1		*REAR DOOR INNER RUBBER O/S	Necessary	215.20 F	*188.10 FL
9	1		*REAR DOOR GLASS OUTER MOULDING O/S	Not Necessary	145.50 F	*- FL
10	2		*REAR DOOR HINGES	Not Necessary	210.00 F	*- FL
11	1		*REAR DOOR CHECKER O/S	Not Necessary	151.00 F	*- FL
12	1		*ROCKER PANEL GARNISH O/S	Grazed / Torn	981.20 F	*681.10 FL
13	1		*REAR FENDER O/S	Repair	1,219.10 F	*- FL
14	1		*REAR FENDER OUTER GARNISH O/S	Grazed	485.20 F	*322.50 FL
15	1		*REAR SHOCK ABSORBER O/S	Not Necessary	392.20 F	*- FL
16	1		*REAR WHEEL HUB BEARING O/S	Damaged	650.00 F	*520.00 FL
17	1		*REAR KNUCKLE ARM O/S	Bent	855.20 F	*655.20 FL
18	1		*REAR TRAILING ARM O/S	Bent	615.20 F	*380.50 FL
19	1		*REAR CROSS MEMBER	Not Necessary	1,455.80 F	*- FL
20	1		*REAR BUMPER	Repair	981.20 F	*- FL
21	1		*REAR BUMPER PAD	Grazed	655.20 F	*456.10 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
23	1		*REAR SPORT RIM O/S 20 INCH	Bent / Warped	1,800.00 FS	*880.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,329.20	6,178.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,324.58

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	16,329.20
						4,853.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER O/S DOOR MECHANISM	New	180.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	0.00
5	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	280.00	120.00
6	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,000.00	400.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	700.00
Gross Labour Cost (S\$)			3,430.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >