



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6224P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	499.90	499.90
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER LOWER COVER	DEFORMED	552.60	552.60
1	RETAINER, REAR BUMPER SIDE LH	DEFORMED	94.80	94.80
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR BUMPER LOWER COVER LH	DEFORMED	148.40	148.40
1	TAILLAMP LH LOWER	CRACKED	548.40	548.40
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
	LESS 25% DISCOUNT		-494.83	-494.83
			1,484.47	1,484.47
<u>SPECIAL NETT ITEMS</u>				
1	REAR TRUNK APP STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK COMFORT & TEL NO STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			150.00	150.00
<u>LABOUR</u>				
	PANEL BEATING.		400.00	250.00
	SPRAY PAINTING CHARGE.		600.00	300.00
	WIRING CHARGE.		50.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
	TUFF KOTE.		50.00	40.00
			1,180.00	650.00
GRAND TOTAL			2,814.47	2,284.47

Report Ref No. NS/INC21005386/Ntce2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,850.00
---	--	--	-----------------

Report Ref No. NS/INC21005386/Ntce2



MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.