

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5430J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
2	REAR BUMPER STAY LH/RH @\$138.10	SERVICEABLE	276.20	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPET TOW COVER	SERVICEABLE	98.80	-
2	REAR BUMPER BRACKET LH/RH @\$55.80	SERVICEABLE	111.60	-
	LESS 20% DISCOUNT		-362.81	-94.65
			1,451.24	378.60
	SPECIAL NETT ITEMS			
1	BUMPER MAT (SN)	NOT NECESSARY	50.00	-
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	180.00	-
			230.00	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	350.00
	SPRAY PAINTING CHARGE.		400.00	250.00
	TUFF KOTE.		60.00	40.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			1,120.00	670.00
	GRAND TOTAL		2,801.24	1,048.60

Report Ref No. NS/INC21005387/Nvcn2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

T

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser