

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



| AUTOMOBILE INSPECTION REPORT   |   |                                     |         |            |                    |  |
|--|---|-------------------------------------|---------|------------|--------------------|--|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21005387/Nvcn2       |   |                                     |         |            |                    |  |
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556 |   |                                     | Date:   | 19-05-2021 |                    |  |
|  |   |                                     | Code:   | INC4       |                    |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                             |   |                                     |         |            |                    |  |
|  | Insured Veh.  | SLE 7569L                           | Veh. Ir | nspected   | SHA 5430J          |  |
|  | Policy No.  |                                     | Cover   | age (\$)   | 0.00               |  |
|  | Claim No.   | MT/1130020-002                      | Exces   | s (\$)     | 0.00               |  |
|  | Assign From   |                                     | Assig   | n Date     | 30/04/2021         |  |
| 2. Vehicle Particulars & Condition                                     |   |                                     |         |            |                    |  |
|  | Make & Model  | HYUNDAI IONIQ                       | c.c     |            | 1580               |  |
|  | Engine No.  | HIDDEN                              | Year o  | f Reg.     | 2019               |  |
|  | Chassis No.   | KMHC851CVLU187972                   | Colou   | r          | BLUE               |  |
|  | Odometer  | 118910                              | Steeri  | ng         | IN ORDER           |  |
|  | Brakes  | IN ORDER                            | Modifi  | cation     | STANDARD ALLOY RIM |  |
|  | General   | FAIR                                |         |            |                    |  |
| 3. Conditions of Tyres   |   |                                     |         |            |                    |  |
|  |   | Size                                | Make    |            | Balance            |  |
|  | R/H Front Tyre  | 195/65 R15                          | MOZZC   | )          | 4 mm               |  |
|  | L/H Front Tyre  | 195/65 R15                          | MOZZC   | )          | 4 mm               |  |
|  | R/H Rear Tyre   | 195/65 R15                          | MOZZC   | )          | 5 mm               |  |
|  | L/H Rear Tyre   | 195/65 R15                          | MOZZC   | )          | 5 mm               |  |
| 4. Description of Damages  |   |                                     |         |            |                    |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  |                                     |         |            |                    |  |
|  | DAMAGES SEE DETAILS.  |                                     |         |            |                    |  |
| 5.   | General Information   |                                     |         |            |                    |  |
|  | Accident Date   | 29/04/2021                          | Inspec  | tion Date  | 30/04/2021         |  |
|  | Survey held at COMFORTDELGRO ENGINEERING PTE LTD  |                                     |         |            |                    |  |
|  |   | 59 LOYANG DRIVE<br>SINGAPORE 508969 |         |            |                    |  |
| 5a. Remarks  |   |                                     |         |            |                    |  |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                     |         |            |                    |  |
| 5b.  | 5b. Estimate Days of Repair   |                                     |         |            |                    |  |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days  |                                     |         |            |                    |  |
|  |   |                                     |         |            |                    |  |