

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005393/KGA3Q2**Date:** 29/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070086565
Claimant Vehicle No :	SJF1138E	Insured Vehicle No :	GBE8528S
Date of Loss:	30/04/2021	Nature of Claim:	TP
		Claim No:	8813900235SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF1138E	Engine No:	CAV444096
Make & Model:	VOLKSWAGEN GOLF, 1.4 (A)	Chassis No:	WVWZZZ1KZDK004086
Reg. Date:	11/10/2012 (Man. Year: 2012)	Odometer:	172789 km
Colour:	Metallic Red		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,398.00	3,396.82	7,001.18	67.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,225.00	1,120.00	1,105.00	49.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,623.00	4,516.82	8,106.18	64.22
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	12,623.00	3,550.00	9,073.00	71.88
+ GST 7.00/7.00% (S\$)	883.61	248.50	635.11	71.88
Nett Amount (S\$)	13,506.61	3,798.50	9,708.11	71.88
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		4,198.50		
Global Sum Settlement (S\$)		4,150.00		

INSPECTION

Date of Assignment:	03/05/2021	Wega Engineering Pte Ltd (HQ)
Date Inspected:	04/05/2021 Inspected At:	BLK 176 Sin Ming Drive #04-16, Sin Ming
		AutoCare
		Singapore 57521
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	1,140.00 F	*1,140.00 FL
2	1		*FRONT HEADLAMP RH	Serviceable	761.00 F	*- FL
3	1		*FRONT FENDER RH	Bent	649.00 F	*649.00 FL
4	1		*FRONT FENDER BRACKET RH (TOP PANEL)	Repair	61.00 F	*- FL
5	1		*FRONT BUMPER BRACKET RH	Distorted	53.00 F	*53.00 FL
6	1		*FRONT FOG LAMP COVER RH	Serviceable	104.00 F	*- FL
7	1		*FRONT FOG LAMP RH	Serviceable	245.00 F	*- FL
8	1		*FRONT SPORT RIM RH	Serviceable	1,473.00 F	*- FL
9	1		*FRONT TYRE RH	Serviceable	225.00 F	*- FL
10	1		*FRONT KNUCKLE ARM RH	Bent	758.00 F	*631.60 FL
11	1		*FRONT WHEEL HUP RH	Not Necessary	589.00 F	*- FL
12	1		*FRONT WHEEL BEARING RH	Necessary	280.00 F	*280.00 FL
13	1		*FRONT LOWER ARM RH	Distorted	487.00 F	*436.00 FL
14	1		*FRONT ABSORBER RH	Bent	484.00 F	*386.00 FL
15	1		*FRONT TIE ROD RH	Serviceable	166.00 F	*- FL
16	1		*FRONT TIE ROD INNER RH	Serviceable	122.00 F	*- FL
17	1		*FRONT TORSION BAR LINK RH	Serviceable	125.00 F	*- FL
18	1		*FRONT DRIVE SHAFT ASSY RH	Repair	2,676.00 F	*- FL
					Sub Total (\$\$)	10,398.00 3,575.60
					- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00 178.78
					Total Parts (\$\$)	10,398.00 3,396.82

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	20.00
2	TO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	70.00
3	TO REMOVE AND REFIX UNDERCARRIAGE	New	600.00	200.00
4	TO RESPRAY ACCIDENT FRONT PORTION	New	600.00	400.00
5	TO KNOCKING AND WELDING FRONT PORTION	New	500.00	400.00
6	TO APPLY RUST PROOFING TO AFFECTED AREA	New	150.00	30.00
7	TO REPLACE FRONT TYRE	New	55.00	0.00
8	TO CHECK FOR FUNCTION AND ALIGNMENT HEADLAMP	New	80.00	0.00
Gross Labour Cost (\$)			2,225.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >