

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21005394/ARA3Q2
Date: 29/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100503555-04
Claimant Vehicle No :	SLR6471Y	Insured Vehicle No :	SKM4360K
Date of Loss:	02/05/2021	Nature of Claim:	TP
		Claim No:	6524809456SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR6471Y		
Make & Model:	HONDA HR-V, 1.5 DX CVT (A)	Engine No:	L15B4532874
Reg. Date:	23/08/2017 (Man. Year: 2017)	Chassis No:	JHMRU1810GX202874
Colour:	Purple	Odometer:	50257 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,838.50	3,331.52	2,506.98	42.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	930.00	1,550.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,318.50	4,261.52	4,056.98	48.77
Approved Total (Overridden) (S\$)		3,400.00		

(S\$)	8,318.50	3,400.00	4,918.50	59.13
+ GST 7.00/7.00% (S\$)	582.30	238.00	344.30	59.13
Nett Amount (S\$)	8,900.80	3,638.00	5,262.80	59.13
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,880.00		

INSPECTION

Date of Assignment: 03/05/2021

Date Inspected: 03/05/2021

Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	495.80 F	*495.80 FL
2	1		*FRONT BUMPER LOWER LIP	Torn	351.00 F	*351.00 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	27.10 F	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	321.00 F	*321.00 FL
5	1		*FRONT BUMPER FOG LAMP COVER RH	Deformed	45.00 F	*45.00 FL
6	1		*FRONT BUMPER FOG LAMP RH	Cracked	327.70 F	*327.70 FL
7	1		*RH FRONT HEADLAMP	Cracked	1,820.90 F	*1,820.90 FL
8	1		*RH FRONT HEADLAMP LOWER BRACKET	Cracked	45.00 F	*45.00 FL
9	1		*RH FRONT FENDER	Not Necessary	582.00 F	*- FL
10	1		*RH FRONT FENDER INNER COWLING	Not Necessary	131.00 F	*- FL
11	1		*RH FRONT FENDER OUTER GARNISH	Deformed	166.00 F	*166.00 FL
12	1		*FRONT GRILLE	Cracked	385.00 F	*385.00 FL
13	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	95.30 F	*- FL
14	1		*FRONT SUPPORT PANEL	Not Necessary	576.20 F	*- FL
15	1		*WASHER TANK	Cracked	169.50 F	*169.50 FL
16	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS
17	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
18	1		*FRONT GRILLE CLIPS	Not Necessary	80.00 FS	*- FS
19	4		*FRONT FENDER INNER COWLING CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,838.50	4,156.90
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	825.38
Total Parts (\$)	5,838.50	3,331.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TUFF KOTE	New	200.00	0.00
3	PANEL BEATING	New	1,000.00	500.00
4	SPRAY PAINTING	New	1,200.00	400.00
Gross Labour Cost (\$\$)			2,480.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >