

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21005399/QBS3Q2**Date:** 06/09/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SCK3138Z	Insured Vehicle No :	SLP6938D
Date of Loss:	26/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001916

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCK3138Z	Engine No:	27696030610032
Make & Model:	MERCEDES-BENZ S400L HYBRID, 3.5 (A)	Chassis No:	WDD2221572A039759
Reg. Date:	19/02/2014 (Man. Year: 2013)	Odometer:	136931 km
Colour:	Black		
Engine Capacity:	3498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/40 R19	Rear Tyre Size:	275/40 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,220.11	5,700.00	1,520.11	21.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	1,180.00	2,700.00	69.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,100.11	6,880.00	4,220.11	38.02
Approved Total (Overridden) (S\$)		5,500.00		

	(S\$)	11,100.11	5,500.00	5,600.11	50.45
+ GST 7.00/7.00% (S\$)		777.01	385.00	392.01	50.45
Nett Amount (S\$)		11,877.12	5,885.00	5,992.12	50.45
+ Car Rental (6.0 x S\$180.00/day) (S\$)			1,080.00		
+ Doc/Search Fee (S\$)			29.00		
			6,994.00		
			6,900.00		

INSPECTION

Date of Assignment: 03/05/2021

Date Inspected: 03/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Vermogen Ace Pte Ltd (Jln Lam Huat) (HQ)

60 Jalan Lam Huat, #03-35/36

Singapore 737869

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2021)
Parts: 143	MERCEDES-BENZ S400L HYBRID 3.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SCK3138Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (NPA)	Repair	0.00 F	*- FL
2	1		*REAR BUMPER SIDE RETAINER RH (NPA)	Serviceable	0.00 F	*- FL
3	1		*REAR BUMPER SIDE BRACKET RH	Broken	89.28 F	*89.28 FL
4	1		*REAR BUMPER MOUNTING RAIL RH (NPA)	Serviceable	0.00 F	*- FL
5	1		*REAR BUMPER REVERSE SENSOR RH (NPA)	Serviceable	0.00 F	*- FL
6	1		*REAR BUMPER SIDE MOULDING RH (NPA)	Serviceable	0.00 F	*- FL
7	1		*SET REAR BUMPER CLIP (NPA)	Serviceable	0.00 F	*- FL
8	1		*REAR FENDER RH	Dented	6,244.05 F	*6,244.05 FL
9	1		*REAR FENDER INNERSHIELD RH (NPA)	Serviceable	0.00 F	*- FL
10	1		*SET REAR FENDER INNERSHIELD CLIPS RH (NPA)	Serviceable	0.00 F	*- FL
11	1		*REAR DOOR RH (NPA)	Serviceable	0.00 F	*- FL
12	1		*REAR DOOR LOWER CHROME MOULDING RH (NPA)	Serviceable	0.00 F	*- FL
13	1		*REAR WINDSCREEN GLASS MOULDING (NPA)	Serviceable	0.00 F	*- FL
14	1		*REAR WINDSCREEN GLASS SEALANT (NPA)	Serviceable	0.00 F	*- FL
15	1		*REAR RIM RH	Serviceable	886.78 F	*- FL
16	1		*REAR TYRE RH (NPA)	Serviceable	0.00 F	*- FL
17	1		*REAR WHEEL BEARING RH (NPA)	Serviceable	0.00 F	*- FL
18	1		*REAR LOWER ARM RH (NPA)	Serviceable	0.00 F	*- FL
19	1		*REAR WHEEL HUB RH (NPA)	Serviceable	0.00 F	*- FL
20	1		*REAR SHOCK ABSORBER RH (NPA)	Serviceable	0.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,220.11	6,333.33
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	633.33
Total Parts (\$\$)	7,220.11	5,700.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA ,TO REMOVE & REFIT DAMAGE PARTS	New	1,500.00	400.00
2	TO PUTTY & RESPRAY ON ACCIDENT AREA ,FRONT RIGHT PORTION	New	1,200.00	600.00
3	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	0.00
4	TO SPRAY RUST PROOF	New	150.00	40.00
5	TO CHECK & REWIRING	New	120.00	40.00
6	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	180.00	100.00
7	TO WHEEL ALIGNMENT	New	150.00	0.00
8	TO DO TYRE BALANCING	New	150.00	0.00
9	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD	New	280.00	0.00
			Gross Labour Cost (\$\$)	1,180.00
			3,880.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >