

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21005408/UTF3Q2
Date: 08/06/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00008002000
Claimant Vehicle No :	FY5032Y	Insured Vehicle No :	PC8092B
Date of Loss:	01/04/2021	Nature of Claim:	TP
		Claim No:	SNM21D201932/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FY5032Y		
Make & Model:	SUZUKI UH200AL6 BURGMAN, 200cc ABS	Engine No:	H405402921
Reg. Date:	07/02/2017 (Man. Year: 2016)	Chassis No:	MLCC91121G0402921
Colour:	Grey	Odometer:	0 km
Engine Capacity:	200 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/90-13	Rear Tyre Size:	130/70-12
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,699.50	2,825.70	2,873.80	50.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	430.00	720.00	62.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,849.50	3,255.70	3,593.80	52.47
Approved Total (Overridden) (S\$)		2,600.00		

Nett Amount (S\$)**6,849.50****2,600.00****4,249.50****62.04**INSPECTION

Date of Assignment: 03/05/2021

Date Inspected: 03/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jun 2021)	
Parts:	N/A	SUZUKI UH200AL6 BURGMAN 200cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FY5032Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FAIRING	Cracked	450.00 FL	*450.00 FL
2	1		*FRONT FAIRING INNER PANEL	Cracked	265.00 FL	*265.00 FL
3	1		*FRONT LOWER FAIRING	Cut	210.00 FL	*210.00 FL
4	1		*HEADLAMP	Cracked	225.00 FL	*225.00 FL
5	1		*FRONT SIGNALS	N/S Broken	310.00 FL	*125.00 FL
6	1		*FRONT MUDGUARD	Cracked	155.00 FL	*155.00 FL
7	1		*FRONT FORK ASSY	Repair	850.00 FL	*- FL
8	1		*FORK UNDER BRACKET	Not Necessary	220.00 FL	*- FL
9	1		*FRONT RIM	Not Necessary	310.00 FL	*- FL
10	1		*FRONT BRAKE DISC	Not Necessary	165.00 FL	*- FL
11	1		*LOWER BELLY PANEL	Cut	285.00 FL	*285.00 FL
12	1		*FRONT RIM SHAFT	Not Necessary	45.00 FL	*- FL
13	1		*WINDSHIELD	Scratched	165.00 FL	*165.00 FL
14	1		*HEADLAMP COVER	Cracked	150.00 FL	*115.00 FL
15	1		*SIDE MIRRORS	N/S Cut	160.00 FL	*80.00 FL
16	1		*HANDLE BAR	Serviceable	125.00 FL	*- FL
17	1		*HANDLE BAR ENDS	N/S Cut	50.00 FL	*25.00 FL
18	2		*BRAKE LEVERS	Not Necessary	64.00 FL	*- FL
19	1		*REAR FAIRING -L/H	Cracked	355.00 FL	*205.00 FL
20	1		*REAR FAIRING PROTECTOR	Distorted	75.00 FL	*75.00 FL
21	1		*FOOTSTEP PANEL	Twisted	105.00 FL	*105.00 FL
22	1		*FOOTSTEP LOWER PANEL	Missing	175.00 FL	*175.00 FL
23	1		*SIDE STAND	Cut	78.00 FL	*78.00 FL
24	1		*MAIN STAND	Repair	120.00 FL	*- FL
25	1		*REAR HANDLE	Cracked	168.00 FL	*120.00 FL
26	1		*CLUTCH COVER	Cut	165.00 FL	*165.00 FL
27	1		*SET NUMBER PLATE (STICKER)	Frt Necessary	28.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
29	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
30	1		*SET STEERING CONE	Not Necessary	90.00 FS	*- FS
31	1		*REAR BOX	Not Necessary	350.00 FS	*- FS
32	1		*REAR BOX BRACKET	Not Necessary	150.00 FS	*- FS
33	1		*STICKER (REAR FENDER N/S)	Necessary	95.00 FS	*95.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,244.00	3,128.00
- List Item Discount on L Items 10.00/10.00% (\$)	544.50	302.30
Total Parts (\$)	5,699.50	2,825.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE (REFER TO RECEIPT)	New	50.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	420.00	380.00
4	TO RESPRAY PAINTING	New	600.00	0.00
Gross Labour Cost (S\$)			1,150.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >