



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
RWONG LAW CORPORATION 123 PENANG ROAD, #06-12, SINGAPORE 238465			Ref: CS/LAW21005411/Dvf3e2	
			Date: 18/10/2021	
			Code: L176	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
	Insured Veh.	YK 2937E	Veh. Inspected	XB 7908R
	Policy No.		Coverage (\$)	0.00
	Claim No.	RW 180900	Excess (\$)	0.00
	Assign From	PEH MUN LING	Assign Date	03/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	NISSAN CWB45AHDN2	c.c	12503
	Engine No.	HIDDEN	Year of Reg.	2002
	Chassis No.	CWB45AH00151	Colour	WHITE
	Odometer	254451 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	10.00 R20	KAPSEN	5 mm
	L/H Front Tyre	10.00 R20	KAPSEN	5 mm
	R/H Rear Tyre	10.00 R20 (D)	GINSTIN	5/5 mm
	L/H Rear Tyre	10.00 R20 (D)	GINSTIN	5/5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/08/2016	Inspection Date	09/07/2021
	Survey held at	HWA SENG BUILDER PTE LTD 76 JOO KOON CIRCLE, SINGAPORE 629096		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	