



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
NTUC INCOME INSURANCE CO-OPERATIVE LTD C/O : TAN CHIN HOE & CO 24 RAFFLES PLACE #24-01 CLIFFORD CENTRESINGAPORE 189556		Ref: CS/LAW21005411/Dvf3e2 Date: 18/10/2021 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	YK 2937E	Veh. Inspected	XB 7908R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/0910584-002	Excess (\$)	0.00
Assign From	PEH MUN LING	Assign Date	03/05/2021
2. Vehicle Particulars & Condition			
Make & Model	NISSAN CWB45AHDN2	c.c	12503
Engine No.	HIDDEN	Year of Reg.	2002
Chassis No.	CWB45AH00151	Colour	WHITE
Odometer	254451 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	10.00 R20	KAPSEN	5 mm
L/H Front Tyre	10.00 R20	KAPSEN	5 mm
R/H Rear Tyre	10.00 R20 (D)	GINSTIN	5/5 mm
L/H Rear Tyre	10.00 R20 (D)	GINSTIN	5/5 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	04/08/2016	Inspection Date	09/07/2021
Survey held at	HWA SENG BUILDER PTE LTD 76 JOO KOON CIRCLE, SINGAPORE 629096		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	