

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC21005419/T1vf3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	17/05/2021	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XB 7892B	Veh. Inspected		XE 2658D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/21/21/VC05/024528	Excess (\$)		0.00	
	Assign From	ONG LI LI	Assign Date		04/05/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI FUSO FP51SD	c.c		11967	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	FP51SDA20139	Colour		BLUE	
	Odometer	314004 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	295/80 R22.5	FIRENZA		6 mm	
	L/H Front Tyre	295/80 R22.5	FIRENZA		6 mm	
	R/H Rear Tyre	295/80 R22.5	FIRENZA		6 mm	
	L/H Rear Tyre	295/80 R22.5	FIRENZA		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information					
	Accident Date	29/04/2021	Inspect Date /	Time	05/05/2021 (04:06 PM)	
	Survey held at	24 SUNGEI KADUT ST 4, 729050 Sungei Kadut				
	Repairer	LYS ENGINEERING				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21005419/T1vf3e2

Inspected By

MOHAMAD TAUFIKH M.MATAI, AMSAE-A K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor