

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	UNITED OVERSEA	AS INSURANCE LTD		Ref:	CS3/UOI21005420/Bqf3e2	
	3 ANSON ROAD #3 SINGAPORE 0799	28-01 SPRINGLEAF TOWER 09		Date:	21/06/2021	
				Code:	UOI2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKW 117X	Veh. Inspected	t	SJH 8867C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	M11D12852105	Excess (\$)		0.00	
	Assign From	JOSEPHINE WONG	Assign Date		04/05/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA WISH	c.c		1794	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	JTDER12W403000679	Colour		BLUE	
	Odometer	216605 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	YOKOHAMA		5 mm	
	L/H Front Tyre	195/65 R15	YOKOHAMA		5 mm	
	R/H Rear Tyre	195/65 R15	YOKOHAMA		5 mm	
	L/H Rear Tyre	195/65 R15	YOKOHAMA		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information					
	Accident Date	01/05/2021	Inspect Date /	Time	04/05/2021 (01:55 PM)	
	Survey held at WAH YU AUTOMOTIVE BODY WORK					
	176 SIN MING DRIVE #05-09 SINGAPORE 575721					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000- \$5,000					
5b.	•	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					

Report Ref No. CS3/UOI21005420/Bqf3e2

Inspected By

LIM TEOW GUAN

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser