

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21005425/R1tce2
	8 SHENTON WAY TOWERSINGAPOR			Date:	17/05/2021
	ATTN: TAN JUN H	ONG		Code:	ASM
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 8981E	Veh. Inspected	l	FBG 3203B
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S1M0376F	Excess (\$)		0.00
	Assign From	TAN JUN HONG	Assign Date		04/05/2021
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA FZ16ST	c.c		153
	Engine No.	HIDDEN	Year of Reg.		2012
	Chassis No.	ME145S094C2005013	Colour		BLACK
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	110/70-17	TRAMAXX		4 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	130/70-17	TRAMAXX		4 mm
	L/H Rear Tyre				mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information				
	Accident Date	01/04/2021	Inspect Date /	Time	04/05/2021 (02:11 PM)
	Survey held at STARK HOLDINGS INN BIKE LEASING PTE LTD				
	149 KAKI BUKIT AVE 1 SHUN LI INDUSTRIAL PARK SINGAPORE 416009				
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21005425/R1tce2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$