

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005426/KRS3Q2
Date: 07/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070151560
Claimant Vehicle No :	GBB2280K	Insured Vehicle No :	SJS1912T
Date of Loss:	03/05/2021	Nature of Claim:	TP
		Claim No:	7714604481SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB2280K	Engine No:	HIDDEN
Make & Model:	MITSUBISHI CANTER, 3.0 D (M)	Chassis No:	FB70BBA10637
Reg. Date:	01/10/2008 (Man. Year: 2008)	Odometer:	129563 km
Colour:	White		
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	205/65 R15 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Michelin 5/5 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Michelin 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,603.00	2,899.00	1,704.00	37.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	1,130.00	2,870.00	71.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,603.00	4,029.00	4,574.00	53.17
Approved Total (Overridden) (S\$)		3,200.00		

	(S\$)	8,603.00	3,200.00	5,403.00	62.80
+ GST 7.00/7.00% (S\$)		602.21	224.00	378.21	62.80
Nett Amount (S\$)		9,205.21	3,424.00	5,781.21	62.80
	Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 04/05/2021

Date Inspected: 05/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117
Singapore 575636

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT HEADLAMP SET RH	Not Necessary	619.00 F	*- FL	
2	1		*FRONT SIGNAL LAMP RH	Broken	206.00 F	*206.00 FL	
3	1		*FRONT SIDE LAMP	Broken	139.00 F	*139.00 FL	
4	1		*FRONT BUMPER	Bent	833.00 F	*833.00 FL	
5	1		*FRONT BUMPER RETAINER	No such part	92.00 F	*- FL	
6	1		*FRONT FENDER RH	Bent	398.00 F	*398.00 FL	
7	1		*STEPPER GARNISH RH	Cracked	346.00 F	*346.00 FL	
8	1		*DOOR RH	Bent	1,910.00 F	*1,910.00 FL	
9	1		*STICKER	Necessary	60.00 FS	*25.00 FS	
					Sub Total (\$\$)	4,603.00	3,857.00
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	958.00
					Total Parts (\$\$)	4,603.00	2,899.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS (FRONT)	New	1,500.00	500.00
2	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	1,500.00	550.00
3	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR	New	250.00	60.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING FOR SIGNAL LIGHT (FRONT HEADLIGHT)	New	150.00	20.00
5	PROVIDE SKILL LABOUR TO WHEEL ALIGNMENT	New	300.00	0.00
6	PROVIDE SKILL LABOUR TO CHECK UNDERCARRIAGE	New	300.00	0.00
Gross Labour Cost (S\$)			4,000.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >