

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5188D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT (DISC 25%)	CRUMPLED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER SUPPORT F/RH (DISC 25%)	BROKEN	76.40	57.30
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.88
1	HEAD LAMP RH (DISC 25%)	SCRATCHED	945.20	708.90
1	FENDER FRT/RH (DISC 25%)	CRUMPLED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	FENDER LINER FRT/RH (DISC 25%)	CRUMPLED	171.70	128.78
1	MIRROR LAMP RH	SERVICEABLE	65.30	-
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY,FR BUMPER LH	SERVICEABLE	250.40	-
1	ARM SUB-ASSY,FR BUMPER RH	SERVICEABLE	250.40	-
1	BRACKET,FR BUMPER	SERVICEABLE	110.40	-
1	COVER,FR BUMPER HOLE RH	SERVICEABLE	18.50	-
1	BUMPER GRILLE SUB.ASSY,LOWER	SERVICEABLE	311.10	-
1	WIRE,ENGINE ROOM,NO 3	SERVICEABLE	242.00	-
1	FOG LAMP RH	SERVICEABLE	295.20	-
1	LENS & BODY,FR TURN RH	SERVICEABLE	511.80	-
1	COVER RADIATOR	SERVICEABLE	122.80	-
1	GRILLE RADIATOR	SERVICEABLE	310.60	-
1	GRILLE RADIATOR LOWER NO 2	SERVICEABLE	94.60	-
1	BUMPER LIP FRONT	SERVICEABLE	139.60	-
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	-
1	UNDER COVER CENTER	SERVICEABLE	448.30	-
1	NUMBER PLATE FRAME	SERVICEABLE	12.00	-
1	NUMBER PLATE	SERVICEABLE	15.00	-
1	HOOD PANEL	SERVICEABLE	748.10	-

Report Ref No. NS/INC21005431/QEvcn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HOOD HINGE LH	SERVICEABLE	55.90	-
1	HOOD HINGE RH	SERVICEABLE	55.90	-
1	HEAD LAMP LH	SERVICEABLE	945.20	-
1	WIPER WASHER INLET	SERVICEABLE	36.90	-
1	WIPER WASHER JAR	SERVICEABLE	180.10	-
1	MOTOR NO 1,WIPER WASHER JAR	SERVICEABLE	239.00	-
1	MOTOR NO 2,WIPER WASHER JAR	SERVICEABLE	240.00	-
1	TUBE & ACCESSORY	SERVICEABLE	631.90	-
1	FENDER PROTECTOR FRT/RH SIDE	SERVICEABLE	113.90	-
1	FENDER LINER PAD,FR WHEEL RH	SERVICEABLE	49.30	-
1	TYRE	SERVICEABLE	126.74	-
1	COVER,OUTER MIRROR,RH	SERVICEABLE	107.40	-
1	MIRROR ASSY,RH	SERVICEABLE	1,307.10	-
1	WHEEL DISC,FRONT	TO REPAIR SEE LABOUR	1,484.20	-
			12,854.14	1,914.92
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF WHEEL DISC,FRONT.		926.00	500.00
	SPRAY PAINT.		1,854.00	550.00
	TO DO WHEEL ALIGNMENT/TYRE BALANCING.		120.00	60.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX WING MIRROR.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,380.00	1,130.00
	GRAND TOTAL		16,234.14	3,044.92





Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		2,450.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC21005431/QEvcn2



Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser