LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III20014724/ATF3E2-1

12/05/2021 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015 **Claimant Vehicle** JTP6174 Insured Vehicle No: SHD3263Y No:

Date of Loss: 23/12/2020 Nature of Claim: TP Claim No: MCT20120474

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JTP6174

Make & Model: HONDA RS150R MANUAL. 149cc **HIDDEN** Engine No:

Reg. Date: 01/01/2019 (Man. Year: 2019) Chassis No: PMKKC2760KB231287

Colour: Odometer: 0 km Red/Black

Engine Capacity: 149 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 90/80 R17 Rear Tyre Size: 100/80 R17 Front Left Side: Rear Left Side: Maxxis 6 mm Maxxis 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,849.70	2,810.40	3,039.30	51.96
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,675.00	720.00	955.00	57.01
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,524.70	3,530.40	3,994.30	53.08
	Approved Total (Overridden) (S\$)		2,800.00		
	Nett Amount (S\$)	7,524.70	2,800.00	4,724.70	62.79

INSPECTION

Date of Assignment: 04/05/2021

Katoom Custom (HQ)

25 KAKI BUKIT ROAD 4# 05-90 Date Inspected: 30/12/2020 Inspected At:

Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: **ADRIAN LING** Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 10 May 2021)

Parts: N/A HONDA RS150R MANUAL 149cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for JTP6174)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FORK ASSY LH	Bent	750.00 FL	*380.00 FL
2	1		*FORK ASSY RH	Bent	750.00 FL	*380.00 FL
3	1		*TRIPLE CLAMP	Serviceable	300.00 FL	*- FL
4	1		*FRONT CLAMP	Bent	150.00 FL	*150.00 FL
5	1		*CONE BEARING	Necessary	110.00 FL	*110.00 FL
6	1		*HANDLBAR	Bent	195.00 FL	*195.00 FL
7	1		*RIDER FOOTREST ASSY RH	Abraded	220.00 FL	*150.00 FL
8	1		*RIDER FOOTREST ASSY LH	Serviceable	220.00 FL	*- FL
9	1		*SET FRONT STEP HOLDER	Bent	102.00 FL	*50.00 FL
10	1		*REAR STEP HOLDER	Bent	102.00 FL	*50.00 FL
11	1		*HEADLAMP HOLDER	Serviceable	380.00 FL	*-FL
12	1		*FRONT LED RH	Abraded / led snapped	55.00 FL	*55.00 FL
13	1		*FRONT LED LH	Broken	55.00 FL	*55.00 FL
14	1		*PILLION FOOTREST ASSY RH	Bent	220.00 FL	*140.00 FL
15	1		*PILLION FOOTREST ASSY LH	Broken	220.00 FL	*140.00 FL
16	1		*REAR BRAKE PUMP	Serviceable	350.00 FL	*- FL
17	1		*BRAKE SWITCH	Serviceable	135.00 FL	*- FL
18	1		*SET RADIATOR HOSE	Serviceable	88.00 FL	*- FL
19	1		*BASKET	Bent / Deformed	225.00 FL	*160.00 FL
20	1		*MIRROR RH	Dislodged / Missing	90.00 FL	*60.00 FL
21	1		*MIRROR LH	Reused	90.00 FL	*- FL
22	1		*SET TAIL	Scraped / Distorted	129.00 FL	*129.00 FL
23	1		*PIPE COVER	Missing / Abarded	155.00 FL	*80.00 FL
24	1		*FRONT TYRE	Serviceable	220.00 FL	*- FL
25	1		*FRONT COWLING	Dented / Cracked	120.00 FL	*120.00 FL
26	1		*FRONT COWLING SUPPORT PANEL	Broken	95.00 FL	*95.00 FL
27	1		*BRAKE LEVER	Bent	22.00 FL	*22.00 FL
28	1		*REAR BRAKE PEDAL	Abraded / Bent	45.00 FL	*45.00 FL
29	1		*FRONT WHEEL AXLE BOLT	Bent	55.00 FL	*55.00 FL
30	1		*FRONT WHEEL FENDER	Broken	40.00 FL	*40.00 FL
31	1		*FRONT SIDE FAIRING RH	Broken	95.00 FL	*95.00 FL
32	1		*DECAL	Necessary	500.00 FS	*250.00 FS
33	1		*ENGINE OIL	Not Applicable	35.00 FS	*- FS
34	1		*COOLANT	Not Applicable	30.00 FS	*- FS
35	1		*GRIP C/BALANCER RH	End abraded	65.00 FS	*65.00 FS
36	1		*FRONT NUMBER PLATE	Missing	15.00 FS	*15.00 FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.		-	

Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	6,428.00 578.30	3,086.00 275.60
Total Parts (S\$)	5,849.70	2,810.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING	New	50.00	40.00
2	PRESS FRAME	New	550.00	300.00
3	RIM REPAIR / REALIGNMENT / BALANCING	New	575.00	80.00
4	LABOUR	New	500.00	300.00
		Gross Labour Cost (S\$)	1,675.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >