5/11/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21005437/R1VF3E2

Date: 11/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070138741

Claimant Vehicle ODI/C45014

CRAY/3461M

No: Insured Vehicle No: SMV3461M

Date of Loss: 02/05/2021 Nature of Claim: TP Claim No: 6660009549SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBK6158H

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KDB046943

Reg. Date: 28/09/2020 (Man. Year: 2020) Chassis No: JTFHT02P609990370

Colour: Grey Odometer: 26662 km

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------|------------|------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 04/05/2021

A-Tec Automotive Pte Ltd (HQ)

Date Inspected: 04/05/2021 Inspected At: 8 Kaki Bukit Avenue 4 # 05-27 Premier

Singapore 415875

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------------|-------------------------------|--------------------|------------|--------|
| 1 | 1 | *FRT BUMPER | Deformed | 0.00 F | *- F |
| 2 | 1 | *BONNET | Bent | 0.00 F | *- F |
| 3 | 1 | *REAR BUMPER | Deformed | 0.00 F | *- F |
| 4 | 1 | *REAR BUMPER SIDE RETAINER RH | Cracked | 0.00 F | *- F |
| 5 | 1 | *REAR END PANEL | Bent | 0.00 F | *- F |
| 6 | 1 | *REAR RH TAILLAMP GARNISH | Deformed | 0.00 F | *- F |
| 7 | 1 | *TAILGATE | Bent | 0.00 F | *- F |
| 8 | 1 | *REAR BODY PANEL RH | Repair | 0.00 F | *- F |
| F=Fra | anchise part. | | · - | | |
| | | | Total Parts (S\$) | 0.00 | 0.00 |
| | | Report was unsubmitted dur | ing this print-out | | |

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >