

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005442/BPA3Q2
Date: 19/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070009940
Claimant Vehicle No :	SCK899E	Insured Vehicle No :	SMR9272Z
Date of Loss:	30/04/2021	Nature of Claim:	TP
		Claim No:	1529561813SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCK899E		
Make & Model:	BMW 520I, 2.0 L AT D/AB 2WD 4DR GAS/D NAV (A)	Engine No:	A9430433N20B20B
Reg. Date:	28/03/2013 (Man. Year: 2013)	Chassis No:	WBAXG12080DX53052
Colour:	Black	Odometer:	114769 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/35 R20	Rear Tyre Size:	275/30 R20
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,233.49	8,833.82	11,399.67	56.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	2,080.00	3,170.00	60.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,483.49	10,913.82	14,569.67	57.17
Approved Total (Overridden) (S\$)		8,750.00		

(S\$)	25,483.49	8,750.00	16,733.49	65.66
+ GST 7.00/7.00% (S\$)	1,783.84	612.50	1,171.34	65.66
Nett Amount (S\$)	27,267.33	9,362.50	17,904.83	65.66
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,069.95		
Global Sum Settlement (S\$)		10,000.00		

INSPECTION

Date of Assignment: 04/05/2021

Date Inspected: 04/05/2021

Estimated Period of Repair: 6.0 days

Inspected At:

8 kaki bukit ave 4 Premier # 01-24

Repairer: RICO 60 AUTO SERVICES PTE LTD (HQ)

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,680.00 FL	*1,680.00 FL
2	1		*BOOT LID LOGO	Necessary	96.00 FL	*39.00 FL
3	1		*BOOT LID EMBLEM (520I)	Necessary	97.00 FL	*64.10 FL
4	2		*BOOT LID REFLECTOR	Not Damaged	1,316.00 FL	*- FL
5	1		*BOOT LID INNER LOCK	Jammed	552.00 FL	*315.00 FL
6	1		*BOOT LID LOCK CATCH	Not Damaged	66.00 FL	*- FL
7	1		*BOOT LID WEATHERSTRIP	Torn	217.90 FL	*126.80 FL
8	1		*BOOT LID INNER TRIM	Not Damaged	255.00 FL	*- FL
9	1		*BOOT LID SIDE STOPPER	Not Damaged	180.00 FL	*- FL
10	1		*BOOT LID DETECTOR	Broken	321.00 FL	*280.00 FL
11	1		*REAR BUMPER	Broken	1,782.00 FL	*1,531.22 FL
12	2		*REAR BUMPER SIDE BRACKET (PLASTIC)	Broken	228.00 FL	*228.00 FL
13	1		*REAR BUMPER CENTER BRACKET (CENTER)	Broken	298.00 FL	*150.00 FL
14	2		*REAR BUMPER BOLT COVER	Not Necessary	118.00 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Bent	791.00 FL	*418.60 FL
16	1		*REAR BUMPER TOWING COVER	Not Necessary	39.60 FL	*- FL
17	2		*REAR BUMPER SENSOR	Scratched	1,256.00 FL	*450.90 FL
18	1		*REAR BUMPER SENSOR WIREHARNES	Cut	698.00 FL	*165.20 FL
19	4		*REAR BUMPER SENSOR HOLDER	Necessary	124.80 FL	*124.80 FL
20	1		*REAR BUMPER SENSOR BRACKET	Not Necessary	120.00 FL	*- FL
21	1		*REAR BUMPER LOWER GARNISH (CENTER)	Broken	195.00 FL	*109.35 FL
22	1		*REAR BUMPER LOWER GARNISH (SIDE)	Broken	258.00 FL	*106.00 FL
23	2		*REAR BUMPER REFLECTOR	Broken	356.00 FL	*92.40 FL
24	1		*CONTROL SMART OPENER SENSOR 2	Scratched	384.00 FL	*314.72 FL
25	1		*CONTROL SMART OPENER SENSOR 1	Scratched	526.00 FL	*414.72 FL
26	1		*CONTROL SMART OPENER SENSOR UNIT ECU	Broken	548.00 FL	*225.00 FL
27	2		*TAIL LAMP	Broken	1,508.00 FL	*1,100.00 FL
28	2		*TAIL LAMP GARNISH	Broken	250.00 FL	*179.80 FL
29	1		*REAR END PANEL	Dented	860.00 FL	*581.30 FL
30	1		*REAR END PANEL TOP GARNISH	Broken	346.00 FL	*225.00 FL
31	1		*REAR FLOOR TOP BOARD	Not Damaged	689.00 FL	*- FL
32	2		*REAR FENDER INNER TRIM	Not Damaged	916.00 FL	*- FL
33	2		*REAR FENDER INNER SHIELD	Not Damaged	438.00 FL	*- FL
34	1		*REAR EXHAUST PIPE	Not Damaged	1,280.00 FL	*- FL
35	2		*REAR EXHAUST MOUNTING	Not Damaged	120.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR EXHAUST PIPE BRACKET	Not Damaged	98.00 FL	*- FL
37	1		*REAR EXHAUST HEAT PLATE	Dented	479.58 FL	*197.90 FL
38	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
39	1		*BOOTLID SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
41	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
42	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
44	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
45	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*80.00 FS
46	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	250.00 FS	*- FS
47	1		*REAR FLOOR TOOLS BOX SEALANT	Not Necessary	150.00 FS	*- FS
48	2		*REAR EXHAUST CHROME HEAD	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,207.88	9,289.81
- List Item Discount on L Items 5.00/5.00% (\$\$)	974.39	455.99
Total Parts (\$\$)	20,233.49	8,833.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	200.00	0.00
4	WIRING CHECK	New	100.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	100.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	120.00
7	TRANFER BOOTLID MECHANISM	New	150.00	80.00
8	CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	REMOVE AND REFIX REAR EXHAUST PIPE	New	350.00	150.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	600.00	0.00
Gross Labour Cost (\$\$)			5,250.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >