



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4204L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR (LH)	BENT	1,789.90	1,789.90
1	REAR DOOR GEAR / REGULATOR (LH)	NOT NECESSARY	367.84	-
1	REAR DOOR POWER MOTOR (LH)	NOT NECESSARY	256.80	-
1	REAR DOOR LOCK ASSY	NOT NECESSARY	306.40	-
1	REAR DOOR TRIM BOARD (LH)	NOT NECESSARY	613.60	-
1	REAR DOOR PROTECTOR (LH)	CUT	166.20	166.20
1	REAR BUMPER	BROKEN	459.40	459.40
1	REAR BUMPER CENTRE MOULDING ASSY	NOT NECESSARY	451.25	-
1	REAR BUMPER SIDE RETAINER (LH)	NOT NECESSARY	85.80	-
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE UNDER (LH)	NOT NECESSARY	123.10	-
1	REAR BUMPER REFLECTOR LAMP (LH)	NOT NECESSARY	82.90	-
1	TAIL LAMP (LH)	NOT NECESSARY	870.40	-
1	REAR FENDER (LH)	DENTED	1,768.30	1,768.30
1	REAR FENDER SHIELD REAR PIECE (LH)	NOT NECESSARY	173.60	-
1	REAR FENDER SHIELD FRT PIECE (LH)	NOT NECESSARY	165.50	-
1	ROCKER PANEL OUTER GARNISH	TO REPAIR SEE LABOUR	715.60	-
1	REAR TYRE RIM (LH)	DISTORTED	1,124.20	1,124.20
1	REAR WHEEL HUP-CAP (LH)	CUT	346.40	346.40
1	REAR WHEELBEARING & HUB ASSY	DAMAGED	554.00	554.00
1	REAR TRAILING ARM (LH)	DISTORTED	265.40	265.40
1	REAR ASSIST (LH)	DISTORTED	227.90	227.90
1	REAR SHOCK ABSORBER (LH)	DISTORTED	230.50	230.50
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	133.10	-
1	REAR ABSORBER STOPPER (LH)	NOT NECESSARY	137.60	-
1	REAR ABSORBER COVER (LH)	NOT NECESSARY	175.60	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,468.70	-
1	STABILIZER BAR	NOT NECESSARY	387.30	-
1	STABILIZER LINK (LH)	NOT NECESSARY	147.30	-
1	REAR UPPER ARM (LH)	DISTORTED	239.50	239.50

Report Ref No. CS/AGI21005444/Dtf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LOWER ARM (LH)	DISTORTED	393.10	393.10
1	REAR KNUCKLE ARM (LH)	DISTORTED	538.10	538.10
	LESS 20% DISCOUNT		-2,957.46	-1,624.98
			11,829.83	6,499.92
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR TEL NO. STICKER (LH) (SN)	NECESSARY	10.00	10.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	REAR TYRE (LH) (SN)	NOT NECESSARY	216.00	-
			306.00	90.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER GARNISH.		1,400.00	800.00
	SPRAY PAINTING CHARGE.		1,200.00	800.00
	WIRING CHARGE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	NOT NECESSARY	150.00	-
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	REMOVE / REFIX UNDERCARRIAGE (RR).		400.00	150.00
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	400.00	-
	REMOVE / REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	REMOVE / REFIX EXHAUST PIPE.	NOT NECESSARY	80.00	-
	TRANSFER OF DOOR MECHANISM REAR.		80.00	60.00
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			4,940.00	2,000.00
GRAND TOTAL			17,075.83	8,589.92

Report Ref No. CS/AGI21005444/Dtf3e2



RECOMMENDED COST OF REPAIRS			8,589.92
-----------------------------	--	--	----------

Report Ref No. CS/AGI21005444/Dtf3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.