

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731 | Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: YP2812E200612

Estimate**Customer**

Name: India International Insurance Pte Ltd

Date: 04-05-21

Address: Motor Claims Department

Vehicle No: YP2812E

64 Cecil Street #04-00 & #05-00

Model/Make: Mitsubishi Fuso

IOB Building

Singapore 049711

FM65FM2RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper	\$ 1,828.25	X
2	Bumper Reinforcement	\$ 1,002.50	X
3	Grille CRA	\$ 795.12	X
4	Grille Inner CRA	\$ 455.10	X
5	Head Lamp AN	\$ 1,003.20	X
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 580.00	- 400
	To putty & spray painting & including touch up paint on accident affected	\$ 750.00	- 450

Total Parts & Labour of estimate for damaged vehicle

\$ 6,464.17

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

→ ~~10~~ LKK Cecil's

M/s Liu's Brother Auto Engrg Wks

Not Authorized
LKK2/5 \$ 2100
4/5/21

2 days.

P-2360.20
252
P-1770.15
L-870
2640.15
202
212

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: