

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21005450/UPA3Q2**Date:** 07/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100285801-09
Claimant Vehicle No :	FBH1338D	Insured Vehicle No :	SDQ6680K
Date of Loss:	28/04/2021	Nature of Claim:	TP
		Claim No:	7340886908SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH1338D	Engine No:	KZ700990
Make & Model:	SYM COMBIZ 125, 125cc	Chassis No:	RFGAPA301DS000992
Reg. Date:	14/03/2013 (Man. Year: 2013)	Odometer:	70186 km
Colour:	White		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	3.50-10	Rear Tyre Size:	3.50-10
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,632.00	1,380.40	3,251.60	70.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	693.00	580.00	113.00	16.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,325.00	1,960.40	3,364.60	63.18
Approved Total (Overridden) (S\$)		1,550.00		
Nett Amount (S\$)	5,325.00	1,550.00	3,775.00	70.89
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	04/05/2021	
Date Inspected:	04/05/2021	Inspected At: Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALIGNMENT BODY	Not Necessary	420.00 F	*- FL
2	2		*BEARING 6201-2NS (NACHI)	Necessary	28.00 F	*28.00 FL
3	1		*BOX AIR FILTER ASSY	Scratched	140.00 F	*140.00 FL
4	1		*CALIPER FRONT ASSY	Repair	217.00 F	*- FL
5	1		*COVER BODY LH	Cracked	103.00 F	*103.00 FL
6	1		*COVER BODY RH	Cracked	103.00 F	*103.00 FL
7	1		*COVER CRANKCASE VBELT	Cut	91.00 F	*91.00 FL
8	1		*COVER FRONT SUB ASSY	Cut	119.00 F	*119.00 FL
9	1		*COVER INNER FRONT	Cut	55.00 F	*55.00 FL
10	1		*COVER LID	*Check	7.00 F	*- FL
11	1		*COVER SIDE LOWER LH	Cut	42.00 F	*42.00 FL
12	1		*COVER SIDE LOWER RH	Not Necessary	42.00 F	*- FL
13	1		*CUSHION SET FRONT LH	Cut	259.00 F	*259.00 FL
14	1		*CUSHION SET FRONT RH	*Check	259.00 F	*- FL
15	1		*DUST SEAL	Necessary	5.00 F	*5.00 FL
16	1		*DUST SEAL 20*32*5	Necessary	5.00 F	*5.00 FL
17	1		*GASKET COVER CRANKCASE L	Necessary	12.00 F	*12.00 FL
18	1		*GASKET EXHAUST PIPE	Necessary	9.00 F	*9.00 FL
19	1		*HANDLE FRONT COVER ASSY	Cut	51.00 F	*51.00 FL
20	1		*HEADLAMP ASSY	Serviceable	146.00 F	*- FL
21	1		*INNER TRAY FRONT	Damaged	21.00 F	*21.00 FL
22	1		*LEVER BRAKE LH	Cut	14.00 F	*14.00 FL
23	1		*LEVER BRAKE RH	Cracked	13.00 F	*13.00 FL
24	1		*LH HANDLE GRIP BK-001U	Necessary	5.00 F	*5.00 FL
25	1		*METER IU (12V) NEW MODEL	*Check	280.00 F	*- FL
26	1		*MUDGUARD FRONT	Broken	79.00 F	*79.00 FL
27	1		*MUDGUARD FRONT B	Broken	7.00 F	*7.00 FL
28	1		*PAD BRAKE DISC FRONT (FIZPOWER)	Not Necessary	21.00 F	*- FL
29	1		*PANEL FLOOR	Distorted	41.00 F	*41.00 FL
30	1		*PIPE EXHAUST ASSY (BENT)	Not Consistent With The Impact	910.00 F	*- FL
31	1		*PLATE DISC BRAKE FRONT	Not Necessary	115.00 F	*- FL
32	1		*RACE BOTTOM CONE	Necessary	14.00 F	*14.00 FL
33	1		*SEAL DUST WASHER	Necessary	5.00 F	*5.00 FL
34	1		*SEAL SPEEDOMETER GEAR	*Check	14.00 F	*- FL
35	1		*SPOILER UNDER FRONT	*Check	96.00 F	*- FL
36	1		*STAND MAIN ASSY	Bent	68.00 F	*68.00 FL
37	1		*STEERING HANDLE COMP	*Check	70.00 F	*- FL
38	1		*STEERING STEM COMP	*Check	203.00 F	*- FL
39	1		*STICKER (SINGAPORE POST) BOX REAR	Necessary	47.00 F	*47.00 FL
40	1		*STICKER NUMBER PLATE FRONT (BLACK)	Necessary	20.00 F	*20.00 FL
41	1		*VALVE RIM	Not Necessary	13.00 F	*- FL
42	2		*WASHER OIL BOLT	Not Necessary	4.00 F	*- FL
43	1		*WHEEL AXLE FRONT	Not Necessary	13.00 F	*- FL
44	1		*WHEEL CAST FRONT	*Check	257.00 F	*- FL
45	1		*REPAIR ON REAR FIBRE BOX	Damaged	189.00 FS	*160.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,632.00	1,516.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	135.60
Total Parts (\$)	4,632.00	1,380.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES	New	56.00	30.00
2	SPRAY PAINT ON REAR FIBRE BOX	New	259.00	250.00
3	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	378.00	300.00
Gross Labour Cost (S\$)			693.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >