



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFK 52X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	881.90	821.10
1	FRONT BUMPER FOG LAMP-RH	CRACKED	361.90	361.90
1	FRONT BUMPER FOG LAMP COVER-RH	TWISTED	89.90	89.90
1	FRONT BUMPER SIDE GRILLE-RH	TWISTED	68.85	68.85
1	FRONT BUMPER SPONGE	TORN	131.92	131.92
1	FRONT BUMPER REINFORCEMENT	DENTED	477.65	477.65
2	FRONT BUMPER SIDE RETAINERS-L/R @\$48.85	O/S BENT	97.70	48.85
1	FRONT BONNET	NOT NECESSARY	1,029.60	-
1	FRONT BONNET LOGO	NOT NECESSARY	89.60	-
1	FRONT FENDER-RH	DENTED / BENT	786.95	786.95
1	FRONT FENDER INNER SHIELD	DEFORMED / TORN	154.43	154.43
1	SET FRONT FENDER INNER SHIELD CLIPS	NECESSARY	82.50	45.00
1	FRONT FENDER SIGNAL LAMP	NOT NECESSARY	48.60	-
1	FRONT HEADLAMP ASSY	CRACKED	2,286.90	2,066.10
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	1,155.60	-
1	FRONT SHOCK ABSORBER-RH	NOT NECESSARY	481.90	-
1	FRONT LOWER ARM-RH	NOT NECESSARY	560.90	-
1	WASHER TANK-RH	DEFORMED	181.95	181.95
	LESS 25% DISCOUNT		-2,242.19	-1,308.65
			6,726.56	3,925.95
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	45.00	40.00
1	FRONT TYRE-RH (SN)	NOT NECESSARY	280.00	-
			325.00	40.00
	<u>LABOUR</u>			
	TO CHECK FRONT ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE,REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	200.00	-
	TO CHECK WHEEL ALIGNMENT.		120.00	60.00
	TO RESPRAY UNDERCOATING.		80.00	30.00

Report Ref No. CS/AGI21005455/Utf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING AND ETC. PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,080.00 950.00 2,480.00	500.00 450.00 1,060.00
GRAND TOTAL			9,531.56	5,025.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/AGI21005455/Utf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.