

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21005462/KRA3Q2
Date: 20/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900152171
Claimant Vehicle No :	SHF591J	Insured Vehicle No :	SDL5252X
Date of Loss:	25/04/2021	Nature of Claim:	TP
		Claim No:	1618971084SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF591J		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H18818
Reg. Date:	13/11/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU203092709
Colour:	Metallic Pearl White/Red	Odometer:	44050 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,270.95	1,145.32	9,125.63	88.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,010.00	2,580.00	71.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,860.95	2,155.32	11,705.63	84.45
+ GST 7.00/7.00% (S\$)	970.27	150.87	819.40	84.45

Nett Amount (S\$)	14,831.22	2,306.19	12,525.03	84.45
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$81.13/day) (S\$)		324.52		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,838.16		

INSPECTION

Date of Assignment: 03/05/2021

Date Inspected: 03/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,FRONT DOOR ,LH	Repair	1,300.70 FL	*- FL
2	1		*WEATHERSTRIP ,FRONT DOOR ,LH	Serviceable	231.30 FL	*- FL
3	1		*HINGE ASSY ,FRONT DOOR ,LOWER RH	Repair	110.60 FL	*- FL
4	1		*HINGE ASSY ,FRONT DOOR ,UPPER LH	Repair	97.50 FL	*- FL
5	1		*TAPE ,BLACK OUT ,NO.1 FRT LH	Not Necessary	13.30 FL	*- FL
6	1		*TAPE ,BLACK OUT ,NO.2 FRT LH	Not Necessary	43.50 FL	*- FL
7	1		*TAPE ,BLACK OUT ,NO.3 FRT LH	Not Necessary	26.30 FL	*- FL
8	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,FRT LH	Serviceable	926.00 FL	*- FL
9	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,LH	Serviceable	238.30 FL	*- FL
10	1		*FRAME SUB -ASSY FRONT DOOR OUTSIDE HANDLE ,LH	Serviceable	193.50 FL	*- FL
11	1		*HANDLE ASSY ,FRONT DOOR OUTSIDE ,LH	Serviceable	390.60 FL	*- FL
12	1		*PANEL SUN-ASSY ,REAR DOOR ,LH	Bent	1,294.90 FL	*1,294.90 FL
13	1		*WEATHERSTRIP ,REAR DOOR OPENING TRIM ,LH	Serviceable	293.00 FL	*- FL
14	1		*HINGE ASSY ,REAR DOOR ,LOWER LH	Repair	87.10 FL	*- FL
15	1		*HINGE ASSY ,REAR DOOR ,UPPER LH	Repair	98.90 FL	*- FL
16	1		*TAPE, BLACK OUT,NO.1 REAR LH	Necessary	21.90 FL	*21.90 FL
17	1		*TAPE, BLACK OUT,NO.2 REAR LH	Necessary	34.90 FL	*34.90 FL
18	1		*TAPE, BLACK OUT,NO.3 REAR LH	Necessary	15.40 FL	*15.40 FL
19	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,LH	Serviceable	926.00 FL	*- FL
20	1		*REGULATOR SUB-ASSY ,REAR DOOR WINDOW ,LH	Serviceable	206.70 FL	*- FL
21	1		*PANEL SUB-ASSY ,QUARTER LH	Repair	871.50 FL	*- FL
22	1		*LINER ,REAR WHEEL HOUSE ,LH	Serviceable	139.80 FL	*- FL
23	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Serviceable	594.80 FL	*- FL
24	1		*PANEL SUB-ASSY ,QUARTER LH	Repair	871.50 FL	*- FL
25	1		*LINER ,REAR WHEEL HOUSE ,LH	Serviceable	139.80 FL	*- FL
26	1		*COVER,REAR BUMPER	Serviceable	485.60 FL	*- FL
27	1		*FENDER CLIP	Not Necessary	65.00 FS	*- FS
28	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
29	1		*FRT BUMPER CLIP	Not Necessary	65.00 FS	*- FS
30	2		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	130.00 FS	*- FS
31	1		*DOOR STICKER TRANSCAB	Necessary	100.00 FS	*60.00 FS
32	1		*DOOR STICKER 65553333	Necessary	100.00 FS	*60.00 FS
33	1		*TYRE	Serviceable	350.00 FS	*- FS
34	1		*RIM	Serviceable	1,879.40 FS	*- FS
35	1		*HUB CAP	Serviceable	211.50 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET CLIP ,ROCKER PANEL MOULDING	Not Necessary	65.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					12,684.30	1,487.10
- List Item Discount on L Items 25.00/25.00% (S\$)					2,413.35	341.78
Total Parts (S\$)					10,270.95	1,145.32
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,400.00	300.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	660.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (S\$)			3,590.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >