

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/III21005463/APA3Q2

Date:

16/09/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MFL0005549_01

Claimant Vehicle No : GBG8079K**Insured Vehicle No :**

GBK3838Z

Date of Loss: 27/04/2021

Nature of Claim:

TP

Claim No:

MFL2021D0001993

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBG8079K**

Make & Model: NISSAN NV200, 1.5 ABS AIRBAG 2WD 6DR EURO E5 W/RC (M)

Engine No:

K9KC400D057537

Reg. Date: 02/11/2017 (Man. Year: 2017)

Chassis No:

VSKYBAM20Z0146620

Colour: White

Odometer:

114910 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size:

175/70 R14

Front Left Side: Sincera 6 mm

Rear Left Side:

Sincera 6 mm

Front Right Side: Sincera 6 mm

Rear Right Side:

Sincera 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,151.00	9,924.46	5,226.54	34.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	2,880.00	2,270.00	44.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,301.00	12,804.46	7,496.54	36.93
Approved Total (Overridden) (S\$)		10,200.00		

Nett Amount (S\$)	20,301.00	10,200.00	10,101.00	49.76
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,907.45		
Global Sum Settlement (S\$)		10,900.00		

INSPECTION

Date of Assignment: 03/05/2021

Date Inspected: 03/05/2021

Estimated Period of Repair: 11.0 days

Inspected At:

Polymath Garage Pte Ltd - Kaki Bukit (HQ)
 10 KAKI BUKIT ROAD 2, #01-21 FIRST EAST CENTRE
 Singapore 417868

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Jun 2021)	
Parts:	N/A	NISSAN NV200 1.5 ABS AIRBAG 2WD 6DR EURO E5 W/RC (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG8079K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE HOLDER	Dented	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER	Deformed	589.70 F	*589.70 FL
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*FRONT BUMPER SIDE HOLDER	Necessary	70.40 F	*70.40 FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	614.90 F	*- FL
7	1		*FRONT BUMPER SPONGE	Cracked	125.00 F	*125.00 FL
8	1		*FRONT BUMPER TOW COVER	Not Necessary	28.20 F	*- FL
9	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	197.00 F	*- FL
10	2		*FRONT APRON PANEL	Cracked	724.40 F	*724.40 FL
11	1		*FRONT APRON PANEL CLIPS	Necessary	40.00 FS	*40.00 FS
12	1		*FRONT GRILLE	Cracked	338.00 F	*338.00 FL
13	1		*FRONT GRILLE LOGO	Necessary	73.50 F	*73.50 FL
14	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
15	2		*FRONT INNER AIR GUIDE	Not Necessary	76.00 F	*- FL
16	1		*BONNET	Not Necessary	882.00 F	*- FL
17	1		*BONNET LOCK	Not Necessary	78.70 F	*- FL
18	1		*BONNET MOULDING	Not Necessary	150.00 FS	*- FS
19	1		*BONNET ADVERTISEMENT STICKER	Not Necessary	350.00 FS	*- FS
20	2		*HEADLAMP	Cracked	1,230.00 F	*1,230.00 FL
21	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
22	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
23	2		*REAR NUMBER PLATE LAMP	Not Necessary	160.40 F	*- FL
24	1		*REAR BUMPER	Deformed	632.70 F	*632.70 FL
25	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
26	2		*REAR BUMPER SIDE HOLDER	Necessary	84.00 F	*84.00 FL
27	2		*REAR BUMPER REFLECTOR	Missing	123.80 F	*123.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR BUMPER SPONGE	Cracked	94.00 F	*94.00 FL
29	1		*REAR END PANEL OUTER	Dented	345.00 F	*345.00 FL
30	1		*REAR END PANEL INNER	Dented	776.00 F	*776.00 FL
31	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
32	1		*REAR END PANEL TOP GARNISH	Deformed	175.70 F	*175.70 FL
33	2		*TAILLAMP	Cracked	554.00 F	*554.00 FL
34	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
35	1		*TAILGATE LH	Dented	1,469.60 F	*1,469.60 FL
36	1		*TAILGATE LOWER LOCK LH	Damaged	115.00 F	*115.00 FL
37	1		*TAILGATE UPPER LOCK LH	Not Necessary	119.00 F	*- FL
38	1		*TAILGATE OUTER MOULDING LH	Cracked	352.00 F	*352.00 FL
39	1		*TAILGATE LOWER HINGE LH	Not Necessary	107.20 F	*- FL
40	1		*TAILGATE INNER TRIM BOARD LH	Deformed	193.00 F	*193.00 FL
41	1		*TAILGATE INNER TRIM BOARD CLIPS LH	Necessary	20.00 FS	*20.00 FS
42	1		*TAILGATE GLASS SEALANT LH	Necessary	40.00 FS	*40.00 FS
43	1		*TAILGATE SURROUND MOULDING LH	Necessary	200.00 FS	*80.00 FS
44	1		*TAILGATE CAMERA LH	Not Necessary	480.00 FS	*- FS
45	1		*TAILGATE ADVERTISEMENT STICKER LH	Necessary	120.00 FS	*80.00 FS
46	1		*NV200 WORDING	Necessary	141.70 F	*141.70 FL
47	1		*NISSAN LOGO	Necessary	64.90 F	*64.90 FL
48	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
49	1		*TAILGATE RH	Dented	1,102.00 F	*1,102.00 FL
50	1		*TAILGATE LOWER LOCK RH	Damaged	115.00 F	*115.00 FL
51	1		*TAILGATE UPPER LOCK RH	Not Necessary	119.00 F	*- FL
52	1		*TAILGATE LOWER HINGE RH	Not Necessary	107.20 F	*- FL
53	1		*TAILGATE INNER TRIM BOARD RH	Deformed	145.00 F	*145.00 FL
54	1		*TAILGATE INNER TRIM BOARD CLIPS RH	Necessary	20.00 FS	*20.00 FS
55	1		*TAILGATE GLASS SEALANT RH	Necessary	40.00 FS	*40.00 FS
56	1		*TAILGATE SURROUND MOULDING RH	Necessary	200.00 FS	*80.00 FS
57	1		*TAILGATE ADVERTISEMENT STICKER RH	Necessary	350.00 FS	*250.00 FS
58	1		*SPARE TYRE CARRIER	Not Necessary	252.00 F	*- FL
59	1		*TAILGATE FRAME WEATHERSTRIPE	Cut	215.00 F	*215.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,151.00	10,909.40
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	984.94
Total Parts (\$)	15,151.00	9,924.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING (FRONT)	New	800.00	400.00
2	SPRAY PAINTING (FRONT)	New	800.00	200.00
3	WIRING (FRONT)	New	50.00	30.00
4	PANEL BEATING (REAR)	New	1,400.00	800.00
5	SPRAY PAINTING (REAR)	New	1,200.00	1,000.00
6	WIRING (REAR)	New	50.00	30.00
7	TO SPRAY TUFF COAT	New	180.00	80.00
8	TO REMOVE REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE REAR CAMERA	New	100.00	50.00
10	TO REMOVE UPHOLSTERY	New	150.00	60.00
11	TO TRANSFER LH AND RH TAILGATE FITTINGS	New	160.00	100.00
12	TO REMOVE LH AND RH TAILGATE GLASSES	New	160.00	80.00
Gross Labour Cost (S\$)			5,150.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >