

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21005469/ATCE2

**Date:** 15/09/2021

### REFERENCE

Insured/Claimant:	POON KOK WAH	Policy No:	2070036973		
Date of Loss:	30/04/2021	Nature of Claim:	OD	Claim No:	1753397690SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN3284A		
Make & Model:	AUDI A3, 999cc TFSI S TRONIC (LED) (A)	Engine No:	CHZB23435
Reg. Date:	31/07/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V6KA079444
Colour:	Grey	Odometer:	34202 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,986.00	12,917.92	11,068.08	46.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,522.00	6,322.00	4,200.00	39.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>34,508.00</b>	<b>19,239.92</b>	<b>15,268.08</b>	<b>44.25</b>
<b>- Excess (S\$)</b>	<b>3,600.00</b>	<b>3,600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>30,908.00</b>	<b>15,639.92</b>	<b>15,268.08</b>	<b>49.40</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,163.56</b>	<b>1,094.79</b>	<b>1,068.77</b>	<b>49.40</b>
<b>Nett Amount (S\$)</b>	<b>33,071.56</b>	<b>16,734.71</b>	<b>16,336.85</b>	<b>49.40</b>

### INSPECTION

Date of Assignment:	05/05/2021		
Date Inspected:	04/05/2021	Inspected At:	24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	9.0 days		

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,016.00 FS	*1,612.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE - LH / RH	Not Necessary	78.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - LOWER	Cracked	160.00 FS	*128.00 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Cracked	297.00 FS	*237.60 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH / RH	N/S Cracked	594.00 FS	*237.60 FS
7	2		*FRONT BUMPER AIR GRILLE - LH / RH	Not Necessary	376.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
9	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
10	1		*STICKER FOR AIR CONDITIONER	Necessary	8.00 FS	*5.68 FS
11	1		*SIGN CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
12	1		*FRONT BUMPER FOAM COVER	Cracked	122.00 FS	*97.20 FS
13	1		*FRONT BUMPER FOAM	Cracked	189.00 FS	*151.20 FS
14	1		*FRONT BUMPER REINFORCEMENT	Bent	795.00 FS	*636.00 FS
15	1		*FRONT FENDER - LH	Buckled	851.00 FS	*680.40 FS
16	8		*FRONT FENDER POP RIVET	Necessary	27.00 FS	*21.12 FS
17	1		*FRONT FENDER ATTACHEMENT PARTS	Not Necessary	72.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - LH FRONT	Buckled	48.00 FS	*37.68 FS
19	1		*FRONT FENDER BRACKET - LH REAR	Not Necessary	28.00 FS	*- FS
20	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	62.00 FS	*- FS
21	1		*FRONT FENDER BRACE - LH	Not Necessary	96.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	169.00 FS	*- FS
23	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	57.00 FS	*- FS
24	1		*LED HEADLIGHT - LH	Cracked	5,455.00 FS	*4,364.00 FS
25	1		*POWER MODULE FOR MAIN LIGHT	Not Necessary	758.00 FS	*- FS
26	1		*CONTROL UNIT FOR LIGHT CONTROL	Not Necessary	557.00 FS	*- FS
27	1		*LED WITH HEAT SINK	Not Necessary	733.00 FS	*- FS
28	1		*HEADLIGHT HOSE - LH	Not Necessary	40.00 FS	*- FS
29	1		*HEADLIGHT WASHER CYLINDER - LH	Not Necessary	142.00 FS	*- FS
30	1		*HEADLIGHT WASHER HOSE	Not Necessary	68.00 FS	*- FS
31	1		*BONNET	Dented	2,745.00 FS	*2,196.00 FS
32	1		*BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
33	1		*BONNET HINGE - LH / RH	N/S Bent	124.00 FS	*48.88 FS
34	1		*BONNET EDGE PROTECTION	Necessary	28.00 FS	*22.00 FS
35	1		*BONNET CATCH HOOK - UPPER	Not Necessary	90.00 FS	*- FS
36	2		*BONNET LOCK STRIKER - LH / RH	Not Necessary	220.00 FS	*- FS
37	2		*BONNET LOCK - LH / RH	Not Necessary	427.00 FS	*- FS
38	1		*BONNET LOCK BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
39	1		*BONNET SOUND ABSORBER	Not Necessary	219.00 FS	*- FS
40	1		*FRONT LOCK CARRIER	Cracked	727.00 FS	*581.60 FS
41	1		*INTAKE AIR GUIDE - LOWER	Not Necessary	56.00 FS	*- FS
42	1		*INTAKE AIR GUIDE COVER	Not Necessary	29.00 FS	*- FS
43	1		*INTAKE AIR GUIDE	Not Necessary	20.00 FS	*- FS
44	1		*A/C CONDENSER	Not Necessary	529.00 FS	*- FS
45	2		*A/C CONDENSER SEAL RING	Not Necessary	20.00 FS	*- FS
46	1		*RADIATOR	Not Necessary	951.00 FS	*- FS
47	1		*ADDITIONAL RADIATOR	Not Necessary	859.00 FS	*- FS
48	2		*RADIATOR BRACKET - LOWER	Not Necessary	82.00 FS	*- FS
49	1		*COOLANT	Necessary	179.00 FS	*143.04 FS
50	1		*RADIATOR AIR GUIDE - LH	Cracked	25.00 FS	*19.44 FS
51	1		*WASH WATER RESERVOIR	Deformed	206.00 FS	*164.40 FS
52	1		*WASH WATER RESERVOIR SEAL	Not Necessary	8.00 FS	*- FS
53	1		*BONNET CATCH HOOK - LOWER	Not Necessary	63.00 FS	*- FS
54	1		*FRONT NUMBER PLATE	Dented	60.00 FS	*60.00 FS
55	1		*SUNDRIES	Necessary	300.00 FS	*25.60 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SIGNAL HORN - LH (Supplementary)	Cracked	200.00 FS	*159.60 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					23,986.00	12,917.92

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,200.00	1,200.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHTSS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
4	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, LHS FRONT FENDER AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	2,750.00
5	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND HINGES	New	3,600.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,522.00</b>	<b>6,322.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >