



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 550H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEEP CUT	1,858.00	1,739.17
2	FRONT BUMPER SIDE RETAINER RH/LH @\$42.00	NOT NECESSARY	84.00	-
1	FRONT FENDER COWLING LH	NOT NECESSARY	195.00	-
1	FRONT DOOR LH	DENTED / BENT	1,765.00	1,652.22
1	FRONT DOOR RUBBER LH	NECESSARY	330.00	305.97
1	FRONT DOOR VIEW MIRROR HOUSING LH	DAMAGED	935.00	935.00
1	FRONT DOOR GLASS LH	CUT	345.00	345.00
1	FRONT DOOR GLASS OUTER MOULDING LH	NOT NECESSARY	278.00	-
1	FRONT DOOR OUTER HANDLE LH	CUT	420.00	388.25
1	ROCKER PANEL OUTER SIDE SKIRT LH	TO REPAIR SEE LABOUR	526.00	-
1	REAR DOOR LH	DENTED / BENT	1,930.00	1,802.16
1	REAR DOOR RUBBER LH	NECESSARY	330.00	305.97
1	REAR DOOR GLASS LH	SERVICEABLE	365.00	-
1	REAR DOOR GLASS OUTER MOULDING LH	SCRATCHED	248.00	221.20
	LESS 10% DISCOUNT		-960.90	-769.49
			8,648.10	6,925.45
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT SPORT RIM LH (SN)	TO REPAIR SEE LABOUR	1,680.00	-
1	SET FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	45.00	-
1	FRONT DOOR GLASS SOLAR FILM LH (SN)	NECESSARY	150.00	80.00
1	REAR DOOR GLASS SOLAR FILM LH (SN)	NOT NECESSARY	150.00	-
			2,025.00	80.00
<b><u>LABOUR</u></b>				
	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER SIDE SKIRT LH AND FRONT SPORT RIM LH.		600.00	400.00
	TO SPRAY PAINTING ON ACCIDENT PARTS.		1,100.00	1,050.00
	4 WHEEL ALIGNMENT.		120.00	60.00
	TO TRANSFER DOOR PARTS.		200.00	60.00

Report Ref No. CS/INC21005472/Uvf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF-KOTE.		90.00	60.00
			2,110.00	1,630.00
GRAND TOTAL			12,783.10	8,635.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				6,900.00

Report Ref No. CS/INC21005472/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.