

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	-	Ref:	CS3/ASM21005476/Bqce2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	I	Date:	16/07/2021	
	ATTN: ANG RICHA	ARD	(	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 6454S	Veh. Inspected		GBE 8766X	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M039BU	Excess (\$)		0.00	
	Assign From	ANG RICHARD	Assign Date		04/05/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA 150 M	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	JTFAT35Y90K204531	Colour		SILVER	
	Odometer	280768 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE		5 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE		5 mm	
	R/H Rear Tyre	155 R12	YOKOHAMA		5 mm	
	L/H Rear Tyre	155 R12	YOKOHAMA		5 mm	
4.	Description of Damages					
	THE VEHICLE SUS	USTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	03/05/2021	Inspect Date / T	ime	05/05/2021 ( 01:44 PM )	
	Survey held at	GARAGE 13 PTE LTD				
		8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b.	. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					

Report Ref No. CS3/ASM21005476/Bqce2

Inspected By

LIM TEOW GUAN

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser