

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21005478/AQF3Q2
Date: 16/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210018695
Claimant Vehicle No :	SMK5795U	Insured Vehicle No :	SMY2849U
Date of Loss:	03/05/2021	Nature of Claim:	TP
		Claim No:	7696838261SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK5795U	Engine No:	2ZR0C72463
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDZS3EU50J035609
Reg. Date:	16/04/2019 (Man. Year: 2018)	Odometer:	212186 km
Colour:	Bronze		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R15	Rear Tyre Size:	205/60R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/16/2021

Adjuster Report

Date of Assignment: 05/05/2021

Date Inspected: 05/05/2021 Inspected At:

Sw Werkz Pte Ltd (HQ)
BLK 25 KAKI BUKIT ROAD 4, #03-67/68 SYNERGY @ KAKI BUKIT
Singapore 417800

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/16/2021

Adjuster Report

MARKET VALUE:\$98,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	0.00 F	*- F
2	1		*FRONT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRONT BUMPER SIDE HOLDER LH	Distorted	0.00 F	*- F
4	1		*FRONT BUMPER SPONGE	Cracked	0.00 F	*- F
5	1		*FRONT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*FRONT BUMPER REINFORCEMENT BRACKET LH	Bent	0.00 F	*- F
7	1		*FRONT BUMPER TOW COVER	Deformed	0.00 F	*- F
8	1		*FRONT BUMPER FOG LAMP	Cracked	0.00 F	*- F
9	1		*FRONT BUMPER DAY RUNNING LIGHT	Cracked	0.00 F	*- F
10	1		*FRONT BUMPER DAY RUNNING LIGHT GARNISH	Distorted	0.00 F	*- F
11	1		*FRONT BUMPER LOWER GRILLE	Deformed	0.00 F	*- F
12	1		*FRONT BUMPER UNDER COVER	Deformed	0.00 F	*- F
13	1		*FRONT BUMPER UNDER COVER CLIPS	Necessary	0.00 F	*- F
14	1		*FRONT BUMPER LOGO	Necessary	0.00 F	*- F
15	1		*FRONT GRILLE	Cracked	0.00 F	*- F
16	1		*FRONT GRILLE CLIPS	Necessary	0.00 F	*- F
17	1		*HEADLAMP LH	Smashed	0.00 F	*- F
18	1		*FRONT FENDER LH	Distorted	0.00 F	*- F
19	1		*FRONT FENDER INNER SHIELD LH	Torn	0.00 F	*- F
20	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	0.00 F	*- F
21	1		*FRONT FENDER EMBLEM LH	Necessary	0.00 F	*- F
22	1		*FRONT FENDER GLASS MOULDING LH	Necessary	0.00 F	*- F
23	1		*FRONT FENDER GLASS SEALANT LH	Necessary	0.00 F	*- F
24	1		*FRONT FENDER BRACKET LH	Bent	0.00 F	*- F
25	1		*FRONT FENDER WHEEL HOUSE LH	Repair	0.00 F	*- F
26	1		*FRONT LH DOOR	Repair	0.00 F	*- F
27	1		*BONNET	Repair	0.00 F	*- F
28	2		*BONNET HINGE	Bent	0.00 F	*- F
29	1		*FRONT SUPPORT PANEL	Distorted	0.00 F	*- F
30	1		*FUSE BOX	Cracked	0.00 F	*- F
31	1		*FRONT LH WHEEL RIM	Cut	0.00 F	*- F
32	1		*FRONT LH WHEEL RIM COVER	Cut	0.00 F	*- F
33	1		*FRONT LH SHOCK ABSORBER	Bent	0.00 F	*- F
34	1		*FRONT LH KNUCKLE ARM	Damaged	0.00 F	*- F
35	1		*FRONT LH WHEEL HUB C/W BEARING	Damaged	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT LH LOWER ARM	Bent	0.00 F	* - F
F=Franchise part.				Total Parts (\$\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >