14	<	1	of 2 ?	>	Þ١	$\bigcirc$	<b>⊕</b>	100%	~		<sub>G</sub>	Find   Next	
----	---	---	--------	---	----	------------	----------	------	---	--	--------------	-------------	--



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En	Automok	pile					
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD		Ref:	CS3/INC21005484/Uuf3					
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	05/05/2021					
				Code:	INC					
1.		Policy Particulars :-	(THIRD PARTY	CLAIM	)					
	Insured Veh.	SLN 9841P	Veh. Inspected	i	SKP 1791D					
	Policy No.		Coverage (\$)		0.00					
	Claim No.	MT/1130386-002	Excess (\$)		0.00					
	Assign From	THERESA VIMALA	Assign Date		05/05/2021					
2.	2. Vehicle Particulars & Condition									
	Make & Model		c.c		0					
	Engine No.	HIDDEN	Year of Reg.							
	Chassis No.		Colour							
	Odometer	-	Steering Modification							
	Brakes									
	General									
3.		Condition	ons of Tyres							
		Size	Make		Balance					
	R/H Front Tyre				mm					
	L/H Front Tyre				mm					
	R/H Rear Tyre				mm					
	L/H Rear Tyre				mm					
4.		Description	n of Damages							
5. General Information										
	Accident Date	03/05/2021	Inspection Dat	te	05/05/2021					
	Survey held at	25 KAKI BUKIT ROAD 4, #03-33	, SYNERGY							
	Repairer -									
5a.	Remarks									
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.									