

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21005486/Dtf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	18/10/2021	
			Code	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGS 3357T	Veh. Inspected	SLN 8273K	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10010134/KY	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	05/05/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA AXIO	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	NKE1657140852	Colour	SILVER	
	Odometer	108153 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/60 R15	YOKOHAMA	5 mm	
	L/H Front Tyre	185/60 R15	YOKOHAMA	5 mm	
	R/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm	
	L/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	02/05/2021	Inspection Date	05/05/2021	
	Survey held at	JWG INTERNATIONAL PTE LTD			
		10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

**5 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: