

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT GREAT AMERICAN INSURANCE COMPANY CS3/GAI21005487/R1uf3e2 Ref: 3 TEMASEK AVENUE #16-01 CENTENNIAL Date: 17/05/2021 **TOWER SINGAPORE 039190** Code: GAI 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SJU 5287C YN 1911U Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. CLMOMVP000001144 Excess (\$) 0.00 SHERY WONG **Assign Date** 05/05/2021 Assign From **Vehicle Particulars & Condition** 2. MITSUBISHI FE83BEOSRDEA Make & Model c.c 2977 HIDDEN 2011 Engine No. Year of Reg. FE83BEA20496 WHITE Chassis No. Colour 188337 KM Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 7.00-16 **SWALLOW** 7 mm SWALLOW 7.00-16 L/H Front Tyre 7 mm 185 R14C (D) **SWALLOW** R/H Rear Tyre 7/7 mm 185 R14C (D) SWALLOW 7/7 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 03/05/2021 07/05/2021 (12:04 PM) Inspect Date / Time Accident Date A-TEC MOTORZ PTE LTD Survey held at 39 WOODLAND CLOSE #02-43 MEGA @WOODLAND SINGAPORE 737856 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Report Ref No. CS3/GAI21005487/R1uf3e2

Estimate Days of Repair

Inspected By

Automotive Assessor

5b.

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

4 Working Days