

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005491/KPA3Q2
Date: 18/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800070785
Claimant Vehicle No :	SMA2019A	Insured Vehicle No :	SMA6970B
Date of Loss:	03/05/2021	Nature of Claim:	TP
		Claim No:	1794964019SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA2019A		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B5462555
Reg. Date:	30/05/2018 (Man. Year: 2018)	Chassis No:	GK81202200
Colour:	Metallic Dark Blue	Odometer:	68456 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,064.96	3,307.60	1,757.36	34.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,200.00	750.00	38.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,014.96	4,507.60	2,507.36	35.74
+ GST 7.00/7.00% (S\$)	491.05	315.53	175.52	35.74

Nett Amount (S\$)	7,506.01	4,823.13	2,682.88	35.74
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,130.58		
Global Sum Settlement (S\$)		5,100.00		

INSPECTION

Date of Assignment: 05/05/2021

Date Inspected: 06/05/2021

Estimated Period of Repair: 5.0 days

 Inspected At: Wei Lee Motor Works (HQ)
 BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32
 Singapore 575644
Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Buckled	517.60 FL	*483.20 FL
2	1		*FENDER INNER PANEL	Repair	345.70 FL	*- FL
3	1		*BONNET	Repair	690.00 FL	*- FL
4	1		*HEADLAMP ,LH	Mtg Cracked	2,315.30 FL	*2,115.20 FL
5	1		*HEADLAMP CHROME	Dented	90.10 FL	*90.10 FL
6	1		*HEADLAMP LOWER BRACKET	Cracked	40.90 FL	*40.90 FL
7	1		*CENTER GRILLE -CHROME	Serviceable	353.70 FL	*- FL
8	1		*FRONT BUMPER	Bent	923.70 FL	*923.70 FL
9	1		*FRONT BUMPER RETAINER ,LH	Distorted	34.20 FL	*34.20 FL
10	1		*BUMPER FOGLAMP	Serviceable	305.90 FL	*- FL
11	1		*FENDER COWLING	Cracked	102.20 FL	*102.20 FL
12	1		*COWLING CLIP	Necessary	48.00 FL	*48.00 FL
13	1		*ENGINE LOWER COVER	Serviceable	218.90 FL	*- FL
14	1		*CLIP	Not Necessary	48.00 FL	*- FL
15	1		*FRONT BUMPER ENFORCEMENT	Bent	297.00 FL	*297.00 FL
					Sub Total (\$\$)	6,331.20
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,266.24
					Total Parts (\$\$)	5,064.96

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS REPAIR ALL DENTED AREAS TRANSFER LOWER GRILLE ,RH FOGLAMP N ALL ATTACHMENTS TO NEW BUMPER REPLACE /ALIGN ALL PARTS INTO POSITION	New	950.00	600.00
2	TO SPRAY PAINT	New	1,000.00	600.00
Gross Labour Cost (\$\$)			1,950.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >