

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21005492/T1PA3Q2
Date: 18/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800125091
Claimant Vehicle No :	SJB1225H	Insured Vehicle No :	SLG2636Z
Date of Loss:	01/05/2021	Nature of Claim:	TP
		Claim No:	9129864436SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB1225H		
Make & Model:	HONDA ODYSSEY, 2.4 EXV-S CVT SR (A)	Engine No:	K24W72041329
Reg. Date:	09/10/2017 (Man. Year: 2017)	Chassis No:	JHMRC1890HC203683
Colour:	Grey	Odometer:	100129 km
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,216.80	8,109.60	6,107.20	42.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,600.00	2,530.00	5,070.00	66.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,816.80	10,639.60	11,177.20	51.23
Approved Total (Overridden) (S\$)		8,500.00		

(S\$)	21,816.80	8,500.00	13,316.80	61.04
+ GST 7.00/7.00% (S\$)	1,527.18	595.00	932.18	61.04
Nett Amount (S\$)	23,343.98	9,095.00	14,248.98	61.04
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,851.45		
Global Sum Settlement (S\$)		9,800.00		

INSPECTION

Date of Assignment: 05/05/2021

Date Inspected: 06/05/2021

Estimated Period of Repair: 7.0 days

Inspected At:

AP Automotive Services Pte Ltd (HQ)
 Blk 9006 Tampines Street 93, #01-202
 Singapore 528840

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,052.00 FL	*1,052.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	119.50 FL	*119.50 FL
3	1		*TAILGATE WIPER MOTOR	Not Necessary	642.00 FL	*- FL
4	1		*TAILGATE OUTER GARNISH	Cracked	229.00 FL	*229.00 FL
5	1		*TAILGATE LOGO -HONDA	Necessary	57.00 FL	*57.00 FL
6	1		*TAILGATE CENTER GARNISH -ODYSSEY	Cracked	197.00 FL	*197.00 FL
7	2		*TAILGATE LAMP L+R	Cracked	922.00 FL	*922.00 FL
8	1		*TAILGATE HANDLE OPENER	Cracked	136.00 FL	*136.00 FL
9	2		*TAILGATE NUMBER PLATE LAMP L+R	Not Necessary	130.00 FL	*- FL
10	1		*TAILGATE LOCK	Bent	185.00 FL	*185.00 FL
11	1		*TAILGATE LOCK CATCH	Not Necessary	42.00 FL	*- FL
12	1		*TAILGATE INNER TRIM	Cracked	225.00 FL	*225.00 FL
13	2		*TAILGATE HINGE L+R	Not Necessary	51.00 FL	*- FL
14	2		*TAILGATE DAMPER L+R	Not Necessary	175.00 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Twisted	153.00 FL	*153.00 FL
16	2		*TAIL LAMP L+R	Cut	1,676.00 FL	*1,676.00 FL
17	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	84.00 FL	*- FL
18	2		*TAIL LAMP PANEL L+R	Not Necessary	202.00 FL	*- FL
19	2		*REAR SIDE BUMPER L+R	Deformed	180.00 FL	*180.00 FL
20	2		*REAR SIDE BUMPER RETAINER L+R	Deformed	66.00 FL	*66.00 FL
21	1		*REAR BUMPER	Deformed	705.00 FL	*705.00 FL
22	4		*SET REAR BUMPER REVERSE SENSOR	Not Working	744.00 FL	*744.00 FL
23	2		*REAR BUMPER REFLECTOR L+R	Cut	196.00 FL	*196.00 FL
24	2		*REAR BUMPER REFLECTOR GARNISH L+R	Deformed	144.00 FL	*144.00 FL
25	2		*REAR BUMPER RETAINER L+R	Deformed	102.00 FL	*102.00 FL
26	1		*REAR BUMPER BRACKET	Not Necessary	89.00 FL	*- FL
27	1		*REAR BUMPER UNDERCOVER	Not Necessary	302.00 FL	*- FL
28	2		*REAR FENDER L+R	Not Necessary	2,050.00 FL	*- FL
29	2		*REAR FENDER INNER TRIM L+R	Deformed	1,036.00 FL	*1,036.00 FL
30	2		*REAR FENDER COWLING L+R	Not Necessary	384.00 FL	*- FL
31	1		*END PANEL	Bent	457.00 FL	*457.00 FL
32	1		*END PANEL TOP GARNISH	Deformed	255.00 FL	*255.00 FL
33	1		*FLOOR PANEL	Buckled	1,013.00 FL	*1,013.00 FL
34	1		*FLOOR PANEL TOP MAT	Not Necessary	473.00 FL	*- FL
35	1		*EXHAUST PIPE	Not Necessary	638.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*SET EXHAUST MOUNTING	Not Necessary	64.00 FL	*- FL
37	1		*EXHAUST HEAT SHIELD	Not Necessary	108.00 FL	*- FL
38	1		*TAILGATE WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
39	1		*TAILGATE SPOILER CLIPS	Not Necessary	100.00 FS	*- FS
40	1		*TAILGATE INNER TRIM CLIPS	Necessary	100.00 FS	*20.00 FS
41	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
42	2		*TAIL LAMP PANEL SEALANT	Not Necessary	240.00 FS	*- FS
43	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
44	1		*REAR FENDER SEALANT	Not Necessary	250.00 FS	*- FS
45	2		*REAR FENDER INNER TRIM CLIPS	Necessary	200.00 FS	*30.00 FS
46	2		*REAR FENDER COWLING CLIPS	Necessary	200.00 FS	*20.00 FS
47	1		*END PANEL SEALANT	Necessary	200.00 FS	*40.00 FS
48	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*10.00 FS
49	1		*FLOOR PANEL SEALANT	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,273.50	10,079.50
- List Item Discount on L Items 20.00/20.00% (\$)	3,056.70	1,969.90
Total Parts (\$)	14,216.80	8,109.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	1,000.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	1,200.00
3	TO RNR REAR EXHAUST	New	250.00	80.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION }	New	150.00	30.00
5	TO CHECK WIRING AND TAILGATE LAMP FUNCTION }	New	150.00	0.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
8	TO RNR UNDERCARRIAGE	New	250.00	0.00
9	TO CHECK WHEEL BALANCING	New	250.00	0.00
10	TO CHECK WATER LEAK	New	150.00	30.00
11	TO RNR FUEL TANK	New	250.00	0.00
12	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
13	TO RNR REAR TAILGATE MECHANISM	New	350.00	60.00
14	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
15	TO PERFORM RUST PROOFING	New	200.00	40.00
Gross Labour Cost (S\$)			7,600.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >