




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT   |  |  |   |   |
|--|--|--|---|---|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01 AXA<br>TOWERSINGAPORE 068811<br>ATTN: TAN JUN HONG |  |  | Ref: CS3/ASM21005493/Gqce2<br>Date: 27/05/2021<br>Code: ASM |   |
| 1. Policy Particulars :- (THIRD PARTY CLAIM)   |  |  |   |   |
|  | Insured Veh.   | SHB 4166Z  | Veh. Inspected  | SMN 3907L   |
|  | Policy No.   | VFX/P2419138   | Coverage (\$)   | 0.00  |
|  | Claim No.  | S1M039D2   | Excess (\$)   | 0.00  |
|  | Assign From  | TAN JUN HONG   | Assign Date   | 05/05/2021  |
| 2. Vehicle Particulars & Condition   |  |  |   |   |
|  | Make & Model   | HYUNDAI AVANTE 1.6   | c.c   | 1591  |
|  | Engine No.   | HIDDEN   | Year of Reg.  | 2019  |
|  | Chassis No.  | KMHD841CMLU937582  | Colour  | SILVER  |
|  | Odometer   | 95745 KM   | Steering  | IN ORDER  |
|  | Brakes   | IN ORDER   | Modification  | STANDARD ALLOY RIM  |
|  | General  | GOOD   |   |   |
| 3. Conditions of Tyres   |  |  |   |   |
|  |  | Size   | Make  | Balance   |
|  | R/H Front Tyre   | 195/65 R15   | NEXEN   | 6 mm  |
|  | L/H Front Tyre   | 195/65 R15   | NEXEN   | 6 mm  |
|  | R/H Rear Tyre  | 195/65 R15   | NEXEN   | 6 mm  |
|  | L/H Rear Tyre  | 195/65 R15   | NEXEN   | 6 mm  |
| 4. Description of Damages  |  |  |   |   |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  |  |   |  |
| 5. General Information   |  |  |   |   |
|  | Accident Date  | 02/05/2021   | Inspect Date / Time   | 18/05/2021 ( 04:30 PM )   |
|  | Survey held at   | A-TEC AUTOMOTIVE PTE LTD<br>8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875 |   |   |
| 5a. Remarks  |  |  |   |   |
|  | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.<br>D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 |  |   |   |
| 5b. Estimate Days of Repair  |  |  |   |   |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 4 Working Days  |   |

Report Ref No. CS3/ASM21005493/Gqce2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.