

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21005494/KPS3Q2
Date: 17/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLH9236T	Insured Vehicle No :	SCZ9118M
Date of Loss:	03/05/2021	Nature of Claim:	TP
		Claim No:	4447833317SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH9236T		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	2ZR1857547
Reg. Date:	23/11/2016 (Man. Year: 2016)	Chassis No:	JTDGG20W30J005987
Colour:	Metallic Grey	Odometer:	113514 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,729.71	2,227.91	1,501.80	40.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,360.00	340.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,429.71	3,587.91	1,841.80	33.92
Approved Total (Overridden) (S\$)		2,850.00		

(S\$)	5,429.71	2,850.00	2,579.71	47.51
+ GST 7.00/7.00% (S\$)	380.08	199.50	180.58	47.51
Nett Amount (S\$)	5,809.79	3,049.50	2,760.29	47.51
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,451.50		
Global Sum Settlement (S\$)		3,450.00		

INSPECTION

Date of Assignment: 05/05/2021

Date Inspected: 06/05/2021

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING TOP	Necessary	61.70 FL	*61.70 FL
2	2		*REAR WINDSCREEN MOULDING LH & RH	Necessary	139.08 FL	*139.08 FL
3	1		*REAR WINDSCREEN MOULDING BTM	Necessary	70.20 FL	*70.20 FL
4	1		*TAILGATE	Bent	1,477.30 FL	*1,477.30 FL
5	1		*TAILGATE EMBLEM	Necessary	65.70 FL	*65.70 FL
6	1		*TAILGATE ELEGANCE LOGO	Necessary	45.30 FL	*45.30 FL
7	1		*TAILGATE VALVEMATIC LOGO	Necessary	47.60 FL	*47.60 FL
8	1		*TAILGATE LOCK	Repair	412.70 FL	*- FL
9	1		*TAILGATE INNER TRIMBOARD	Serviceable	363.70 FL	*- FL
10	1		*TAILGATE RUBBER	Serviceable	334.50 FL	*- FL
11	1		*REAR BUMPER	Bent / Cracked	591.80 FL	*591.80 FL
12	1		*REAR BUMPER REFLECTOR LH	Serviceable	56.80 FL	*- FL
13	1		*REAR BUMPER SIDE RETAINER LH	Cracked	97.40 FL	*97.40 FL
14	1		*REAR BUMPER SIDE BRACKET LH	Dented	53.80 FL	*53.80 FL
15	12		*REAR BUMPER CLIPS	Necessary	54.00 FL	*54.00 FL
16	1		*REAR BUMPER EXTENSION -LH (NPA)	Serviceable	0.00 FL	*- FL
17	1		*REAR END PANEL	Repair	536.70 FL	*- FL
18	1		*REAR END PANEL GARNISH	Serviceable	298.00 FL	*- FL
19	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,906.28	2,903.88
- List Item Discount on L Items 25.00/25.00% (\$)	1,176.57	675.97
Total Parts (\$)	3,729.71	2,227.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
2	TO REMOVE AND REINSTALL REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES	New	60.00	60.00
3	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
4	TO SPRAY ANTI -RUST CAOTING ON AFFECTED AREAS	New	60.00	30.00
5	TO DISMANTLE ALL DAMAGED PARTS ,TO CUT & WELD REAR END PANEL TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	600.00	500.00
6	TO SPRAY TAILGATE ,REAR BUMPER ,RR END PANEL ,REAR FENDER LH	New	800.00	600.00
Gross Labour Cost (\$\$)			1,700.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >